

Hans Kurt Toenshoff · Berend Denkena

Basics of Cutting and Abrasive Processes

 Springer

Contents

1	Introduction to the Technology of Cutting and Abrasive Processes	1
1.1	Economic Relevance	1
1.2	Taxonomy	3
1.3	Motions, Angles at the Cutting Edge and Engagement Parameters	4
1.4	Cutting and Abrasive Processes as Black Box Systems	8
1.5	Process Types and Engagement Parameters in Drilling	9
1.6	Process Types and Engagement Parameters in Milling	15
1.7	Questions	18
	References	19
2	Chip Formation	21
2.1	Mechanisms of Chip Formation	21
2.2	Chip Root Analysis	25
2.3	Shear Plane Model	29
2.4	Questions	35
	References	36
3	Chip Control	37
3.1	Chip Volume Ratio and Chip Form Classification	37
3.2	Chip Guidance	38
3.3	Influence of the Workpiece Material	42
3.4	Influence of the Cutting Conditions	45
3.5	Questions	46
	References	48
4	Forces and Powers in Cutting and Abrasive Processes	49
4.1	Empirical Models	50
4.2	Modeling of the Feed Force and the Passive Force	59
4.3	Surface Forces at the Cutting Edge	60

4.4	Analytical Approaches in Plastomechanics	63
4.4.1	Theory by Ernst and Merchant	63
4.4.2	Hucks's Theory	64
4.5	Flow Curves and Constitutive Equations	66
4.6	Numerical Theory	68
4.7	Powers, Torques and Forces in Drilling	70
4.8	Power and Forces in Milling Processes	76
4.9	Questions	80
	References	81
5	Energy Conversion and Temperature	83
5.1	Conversion Effects	83
5.2	Heat Flow	86
5.3	Temperatures of Cutting Wedge and Workpiece	89
5.3.1	Temperature Measurement	89
5.3.2	Temperature Fields	96
5.4	Optimization of the Cutting Wedge	101
5.5	Questions	102
	References	103
6	Modeling and Simulation	105
6.1	Kinematic Simulation	106
6.1.1	Representation of the Workpiece	108
6.1.2	Tool Model	114
6.1.3	Determination of Process Values	115
6.2	Numerical Simulation by FEM	119
6.3	Molecular Dynamic Modeling	123
6.4	Questions	126
	References	126
7	Wear	129
7.1	Wear Forms	129
7.2	Loading	132
7.3	Wear Mechanisms	138
7.4	Tool Life	140
7.5	Tool Life Scatter and Process Reliability	146
7.6	Influence of Work Material on Wear	148
7.6.1	Work Material Composition	149
7.6.2	Melting Procedure	150
7.6.3	Heat Treatment	152
7.7	Rounding of the Cutting Edge	153
7.8	Questions	156
	References	157

8	Cutting Materials	159
8.1	Requirements on Cutting Materials	159
8.2	Tool Steels	163
8.3	High Speed Steels	163
8.4	Stellites	165
8.5	Cemented Carbides	166
8.6	Cermets	174
8.7	Ceramics	176
8.8	Diamond	181
8.8.1	Mono-Crystalline Diamond	181
8.8.2	Polycrystalline Diamond	181
8.9	Boron Nitride	183
8.10	Questions	186
	References	187
9	High Speed Cutting	189
9.1	Definition	189
9.2	Chip Formation	192
9.3	Application	193
9.4	High Power Cutting	196
9.5	High Power Drilling	196
9.6	Questions	198
	References	199
10	Hard Machining, Process Design	201
10.1	Hard Turning	201
10.2	Hard Drilling	207
10.3	Hard Milling	209
10.4	Materials	211
10.5	Chip Formation, Forces and Temperature	212
10.6	Cutting Materials and Tool Wear	217
10.7	Questions	218
	References	219
11	Hard Machining, Component Quality	221
11.1	Macro Geometrical Deviations	221
11.2	Micro Geometrical Properties	224
11.3	Physical Influence	226
11.4	Rolling Fatigue Strength	227
11.5	Fatigue Strength	228
11.6	Sealability	230
11.7	Post-treatment Processes	231
11.7.1	Hard Roller Burnishing	231
11.7.2	Water Peening	233

11.8	Questions	234
	References	235
12	Broaching	237
12.1	Broaching Process	237
12.2	Machine Development	242
12.3	Questions	246
	References	246
13	Grinding	247
13.1	Cutting with Geometrically Undefined Cutting Edges	247
13.2	Grinding Materials	250
13.2.1	Corundum	251
13.2.2	Silicon Carbide	253
13.2.3	Cubic Crystalline Boron Nitride and Diamond	254
13.2.4	Grain Sizes of Grinding Materials	255
13.3	Bonding	257
13.4	Grinding Wheels	258
13.5	Burst Safety of Grinding Wheels	261
13.6	Grinding Processes	265
13.6.1	Input Variables	266
13.6.2	Process Variables	276
13.6.3	Output Variables	279
13.7	Conditioning of Grinding Tools	286
13.7.1	Basics	286
13.7.2	Conditioning of Conventional Grinding Wheels	290
13.7.3	Conditioning of Super Hard Grinding Wheels	292
13.8	Grinding Costs	295
13.9	Questions	296
	References	297
14	Gear Grinding	303
14.1	Introduction	303
14.2	Discontinuous Profile Grinding	308
14.3	Continuous Generating Grinding with Grinding Worms	312
14.4	Continuous Crossed Helical Grinding	316
14.5	Questions	320
	References	321
15	Process Layout and Integration into the Process Chain	325
15.1	Basics of Process Chain Layout	325
15.1.1	Technological Interfaces	326
15.1.2	Process Chain Layout	327
15.2	Process Model Generation	328

15.3	Process Layout Using the Example of “Hard Finishing”	331
15.4	Process Chain Layout Using the Example “Gear Production”	335
15.5	Process Supervision	341
15.6	Questions.	345
	References	346
16	Surface and Subsurface Properties	349
16.1	Surface Properties.	350
	16.1.1 Determination of Surface Properties	351
16.2	Subsurface Properties	355
	16.2.1 Determination of Subsurface Properties.	356
	16.2.2 Effects of Cutting Processes.	362
16.3	Questions.	368
	References	369
17	Cooling Lubrication	371
17.1	Requirements.	371
17.2	Cooling Lubricating Fluids	373
	17.2.1 Not Water-Mixable Cooling Lubricating Fluids	373
	17.2.2 Water-Mixable Cooling Lubricating Fluids	375
	17.2.3 Additivation of Cooling Lubricating Fluids	378
17.3	Use of Cooling Lubricating Fluids in Geometrically Determined Cutting.	380
17.4	Use of Cooling Lubricating Fluid in Grinding	383
	17.4.1 Methods to Determine the Cooling Lubricating Fluid Effect in Grinding	385
	17.4.2 Applications and Effects	387
17.5	Questions.	392
	References	393
18	Appendix	397
18.1	Solution to the Exercise for Chap. 3, Question 9	397
18.2	Solution to the Exercise for Chap. 4, Question 26	397
18.3	Solution to the Exercise for Chap. 5, Question 17	398
18.4	Solution to the Exercise for Chap. 6, Question 25	399