

# Flow Manufacturing – What Went Right, What Went Wrong

101 Mini-Case Studies that Reveal  
Lean's Successes and Failures

By  
Richard J. Schonberger

 **Routledge**  
Taylor & Francis Group

A PRODUCTIVITY PRESS BOOK

---

# Contents

---

Preface .....xi

## **PART I   Advanced Process Improvement Found in the 1980s: 32 Tour Reports (27 U.S.; 5 Other Countries)**

<b>Chapter I-1</b>	Apple Computer, Inc., Fremont, CA, 1988 .....	1
<b>Chapter I-2</b>	Coach Leatherware, New York City, 1987 .....	5
<b>Chapter I-3</b>	KONE Subsidiary, Robbins & Myers, Dayton, OH, 1983–85 .....	10
<b>Chapter I-4</b>	Analog Devices, Inc. (ADI), Wilmington, MA, 1987.....	13
<b>Chapter I-5</b>	Westinghouse, Asheville, NC, 1986.....	19
<b>Chapter I-6</b>	WCM at Associated Equipment Co., St. Louis, MO, 1988.....	22
<b>Chapter I-7</b>	Ahlstrom Pump, Manta, Finland, 1989.....	24
<b>Chapter I-8</b>	Day-Brite Lighting Division of Emerson Electric, Tupelo, MS, 1986 .....	29
<b>Chapter I-9</b>	Appleton Electric Division of Emerson Electric, North Chicago, IL, 1986 .....	34
<b>Chapter I-10</b>	Gleason Tool/Harbor Metal Stamping, Rochester, NY, 1987.....	37
<b>Chapter I-11</b>	Hoover Universal, Tillsonburg, ON, Canada, 1986 .....	41
<b>Chapter I-12</b>	3M Data Products Division, Hutchinson, MN, 1984.....	46
<b>Chapter I-13</b>	3M Graphic Preparation Systems, Weatherford, OK, and St. Paul, MN, 1986.....	49
<b>Chapter I-14</b>	Campbell Soup, Paris, TX, 1985.....	60
<b>Chapter I-15</b>	Mars, Veghel, Netherlands, 1989.....	67

<b>Chapter I-16</b>	Caterpillar Manufacturing Programs, Peoria, IL, 1987 .....	72
<b>Chapter I-17</b>	J. I. Case/Tenneco, East Moline, IL, 1989.....	76
<b>Chapter I-18</b>	Manufacturing at Formica, Evandale, OH, 1988.....	82
<b>Chapter I-19</b>	Sealed Air Corp. (SAC), Fair Lawn, NJ, 1989.....	85
<b>Chapter I-20</b>	Sealed Air Corp., Hodgkins, IL, 1989.....	90
<b>Chapter I-21</b>	Russell Athletic, Alexander City, AL, 1988.....	93
<b>Chapter I-22</b>	BIC Corp., Milford, CT, 1989 .....	96
<b>Chapter I-23</b>	Zanussi, Florence, Italy, 1989 .....	101
<b>Chapter I-24</b>	Interchecks, Inc., Centralia, WA, 1989.....	104
<b>Chapter I-25</b>	Zytec Corp., Redwood Falls, MN, 1987 .....	111
<b>Chapter I-26</b>	Honeywell, Plymouth, MN, 1989 .....	116
<b>Chapter I-27</b>	Charles Machine Works, Perry, OK, 1989.....	120
<b>Chapter I-28</b>	AT&T Little Rock, Little Rock, AR, 1988.....	123
<b>Chapter I-29</b>	Haworth Corp., Holland, MI, 1983 and 1984.....	127
<b>Chapter I-30</b>	Steelcase, Inc., Grand Rapids, MI, 1988 .....	132
<b>Chapter I-31</b>	Steelcase, Inc., Grand Rapids, MI, Jan., 1989.....	139
<b>Chapter I-32</b>	Hon Company, Muscatine, IA, 1987.....	148

**PART II Maturing Process Improvements in the 1990s:  
36 Tour Reports (30 U.S.; 5 Other Countries; and One for a  
Company with Plants on Both Sides of the U.S. Border)**

<b>Chapter II-33</b>	Hon Company, Muscatine, IA, 1990.....	155
<b>Chapter II-34</b>	Steelcase, Inc., Grand Rapids, MI, 1990 .....	162
<b>Chapter II-35</b>	Baldor Electric Co., Fort Smith, AR, 1990 .....	168
<b>Chapter II-36</b>	Miller Brewing Co., Trenton, OH, 1993 .....	173
<b>Chapter II-37</b>	Amtico Co. Ltd., U.K., Division of Courtaulds, 1991 .....	179

<b>Chapter II-38</b>	Eli Lilly, Indianapolis, IN, 1996 .....	183
<b>Chapter II-39</b>	Johnson Controls, Electromechanical Systems Unit (EMSU), Milwaukee, WI, 1990 .....	190
<b>Chapter II-40</b>	Johnson Controls Interiors, Holland, MI, 1999 .....	197
<b>Chapter II-41</b>	Siecor Corp., Hickory, NC, 1990 .....	203
<b>Chapter II-42</b>	Four Seasons Remanufacturing Division, Standard Auto Parts, Coppell, TX, 1994 .....	208
<b>Chapter II-43</b>	East Bay Generator, North Oakland, CA, 1990 .....	216
<b>Chapter II-44</b>	Zanussi—Susegana and Porcia Plants, Italy, 1991.....	219
<b>Chapter II-45</b>	American Steel Service Center (ASSC), Kent, WA, 1992.....	225
<b>Chapter II-46</b>	Mazak Corp., U.S., Florence, KY, 1992.....	229
<b>Chapter II-47</b>	Americold, Gullman, AL, 1999 .....	232
<b>Chapter II-48</b>	Sentrol, Inc., Portland (Tigard), OR, 1992 .....	237
<b>Chapter II-49</b>	DeAcero, Monterrey, México, 1998.....	244
<b>Chapter II-50</b>	OPW Fueling Components Division of Dover Corp, Cincinnati, OH, 1993.....	247
<b>Chapter II-51</b>	Wheelabrator, LaGrange, GA, 1992–93 .....	257
<b>Chapter II-52</b>	Alaris Medical Systems, San Diego, CA and Tijuana, Mexico, 1999 .....	261
<b>Chapter II-53</b>	Rotary Lift, Madison, IN, 1993 .....	273
<b>Chapter II-54</b>	Rotary Lift, Madison, IN, 1999 .....	275
<b>Chapter II-55</b>	Shade Foods, New Century, KS, 1999 .....	281
<b>Chapter II-56</b>	Sonic Innovations, Salt Lake City, UT, 1998 .....	288
<b>Chapter II-57</b>	Precor, Bothel, WA, 1994 .....	292
<b>Chapter II-58</b>	Goulds Pumps, Seneca Falls, NY, 1993.....	299
<b>Chapter II-59</b>	Genie Industries, Redmond, WA, 1994 .....	307
<b>Chapter II-60</b>	Marlow Industries, Dallas, TX, 1999 .....	311
<b>Chapter II-61</b>	MEMC Electronic Materials, St. Peters, MO, 1999.....	316

<b>Chapter II-62</b>	Wainwright Industries, St. Peters, MO, 1999.....	322
<b>Chapter II-63</b>	Prolec/GE, Monterrey, México, 1998 .....	331
<b>Chapter II-64</b>	Dixie Products, Business Unit of James River Corp, Fort Smith, AR, 1990.....	333
<b>Chapter II-65</b>	Amoco Polymers, Alpharetta, GA, 1998 .....	336
<b>Chapter II-66</b>	Intermec Co., Everett, WA, 1998.....	340
<b>Chapter II-67</b>	Foxboro Corp., Intelligent Automation Division, Invensys plc, Foxboro, MA, 1999.....	345
<b>Chapter II-68</b>	Plamex, Tijuana, México – 1995, 1998.....	349

**PART III Advances and Missteps along Process-Improvement Pathways in the 2000s**

<b>Chapter III-69</b>	Gillette Andover Manufacturing Center (AMC), Andover, MA, 2000 .....	355
<b>Chapter III-70</b>	Mark Andy Co., St. Louis, MO, 2001 .....	361
<b>Chapter III-71</b>	Mallinckrodt, Irvine, CA, 2000 .....	368
<b>Chapter III-72</b>	Lozier Corp., Omaha, NE, 2001 .....	376
<b>Chapter III-73</b>	Olympus (Shenzhen) Industrial Ltd., Shenzhen, China, 2003 .....	381
<b>Chapter III-74</b>	Woodhead de México, Cd., de Juárez, 2001 .....	387
<b>Chapter III-75</b>	System Sensor de México, Cd. Juárez, 2001 .....	390
<b>Chapter III-76</b>	Quadrant Homes, Bellevue, WA, 2002 .....	395
<b>Chapter III-77</b>	Ultraframe, Clitheroe, U.K., 2008 .....	398
<b>Chapter III-78</b>	R.W. Lyall, Corona, CA, 2000 .....	403
<b>Chapter III-79</b>	Fender Musical Instruments, Corona, CA, 2001 .....	412
<b>Chapter III-80</b>	Ford Stamping and Assembly, Hermosillo, México, 2011 .....	419
<b>Chapter III-81</b>	Volkswagen, Puebla, México, 2001 .....	426

<b>Chapter III-82</b>	Graco, Inc., Minneapolis, 2003 .....	429
<b>Chapter III-83</b>	Fluke Corp., Everett, WA, 2003.....	434
<b>Chapter III-84</b>	TVS Motor Co., Hosur, Tamil Nadu, India, 2012 .....	438
<b>Chapter III-85</b>	Takata Seat Belts (TSB), Monterrey, México, 2004.....	446
<b>Chapter III-86</b>	Schweitzer Engineering Laboratories (SEL), Pullman, WA, 2003 .....	457
<b>Chapter III-87</b>	Milliken Industrials, Wigan, U.K., 2002 .....	465
<b>Chapter III-88</b>	Lenovo, Shanghai Area, China, 2008 .....	469
<b>Chapter III-89</b>	Nintendo Distribution Center, North Bend, WA, 2008.....	475
<b>Chapter III-90</b>	American Sheet Metal (ASM) and American Integration Technologies (AIT), Chandler, AZ, 2003 .....	479
<b>Chapter III-91</b>	SABMiller, plc, Krakow, Poland, 2008.....	485
<b>Chapter III-92</b>	Hollister Inc., Stuarts Draft, VA, 2009 .....	490
<b>Chapter III-93</b>	Motores John Deere, S.A. de C.V., Torreón, México, 2004.....	497
<b>Chapter III-94</b>	FCI, Cd. Juárez, Chihuahua, México, 2004.....	503
<b>Chapter III-95</b>	GBC Scientific Instruments, Melbourne, Australia, 2004 .....	507
<b>Chapter III-96</b>	O.C. Tanner Co., Salt Lake City, UT, 2003 .....	510
<b>Chapter III-97</b>	AmorePacific, Suwon, Korea, 2003.....	514
<b>Chapter III-98</b>	Boeing 737, Renton, WA – 2010.....	518
<b>Chapter III-99</b>	Gleason Corp., Rochester, NY, 2011.....	528
<b>Chapter III-100</b>	BMW Engines, Steyr, Austria, 2011 .....	532
<b>Chapter III-101</b>	ElectroImpact, Inc., Mukilteo, WA, 2014 .....	534
	Annotated Bibliography .....	539
	Index.....	545