

# Composite Structures: Effects of Defects

*Rani Elhajjar*

University of Wisconsin  
Milwaukee, Wisconsin  
USA

*Peter Grant*

Independent Aviation & Aerospace Professional  
Medford, Oregon  
USA

*Cindy Ashforth*

Federal Aviation Administration  
Seattle, Washington  
USA

**WILEY**

## Contents

### Preface *xi*

- 1 Characteristics of Composites 1**
  - 1.1 Introduction to Behavior 1
  - 1.2 Introduction to Composite Analysis 3
  - 1.3 Failure and Strength Methodologies 5
  - 1.3.1 Lamina Failure Modes and their Influence upon Catastrophic Failure of Multidirectional Laminates 5
  - 1.3.2 Design Values and Environmental Sensitivity 8
  - 1.3.3 Design Values for Unnotched Multidirectional Laminates 11
  - 1.3.4 Design Values for Notched Multidirectional Laminates 12
  - 1.3.5 Material Variability 14
  - 1.3.6 Strain-Based Failure Methodology 15
  - 1.3.7 Composite Fatigue Behavior 15
  - References 16
  
- 2 Design Methodology and Regulatory Requirements 19**
  - 2.1 Regulatory Requirements 19
  - 2.2 Material and Process Specifications 22
  - 2.3 Design Methodology 23
  - 2.4 Design Values for Notched Multidirectional Laminates 24
  - 2.5 Design Values for Bolted Joints 28
  - 2.5.1 Determination of Fastener Loading 29
  - 2.5.2 Failure Analysis at a Loaded and Unloaded Hole 29
  - 2.6 Design Values for Bonded Joints and Bondlines 33
  - 2.7 Design Values for Sandwich Structure 36
  - 2.7.1 Facesheet Tension Design Values 36
  - 2.7.2 Facesheet Compression Design Values 36
  - 2.7.3 Sandwich Flexural Design Values 37
  - 2.7.4 Out-of-Plane Loading 37
  - 2.8 Statistical Allowables 37
  - 2.9 Simulation of Temperature and Moisture Content 39
  - References 40

<b>3</b>	<b>Material, Manufacturing, and Service Defects</b>	<b>43</b>
3.1	Introduction	43
3.1.1	Differentiating Cosmetic from Structural Defects	46
3.2	Defects by Stage of Occurrence	46
3.2.1	Material Precure Defects	46
3.2.1.1	Fiber Damage and Defects	50
3.2.2	Manufacturing Defects	51
3.2.3	Service Defects	54
3.3	Defects by Location: Matrix-Dominated Defects	60
3.3.1	Matrix Degradation Due to Porosity and Voids	60
3.3.2	Matrix Degradation Due to Aged Material	63
3.3.3	Matrix Degradation Due to Errors in Curing (Pressure and Temperature)	64
3.3.4	Matrix Damage with No Fiber Breakage from Impact	67
3.3.5	Matrix Cracking and Crazeing	67
3.3.6	Matrix Degradation Due to Anomalous Moisture Absorption	68
3.3.7	Matrix Degradation Due to UV Radiation or Surface Contamination	69
3.3.8	Matrix Degradation Due to High Temperature Exposure	70
3.3.9	Blisters	72
3.3.10	Matrix Degradation Due to Resin Mixture Error	73
3.4	Defects by Location: Fiber-Dominated Process Defects	73
3.4.1	Fiber Misalignment or Wrinkles	73
3.4.1.1	In-Plane Waviness	73
3.4.1.2	Out-of-Plane Waviness	74
3.4.2	Excessive Ply Drops and Gaps	76
3.4.3	Fiber Damage	78
3.5	Defects by Location: Sandwich Composite Defects	78
3.5.1	Core Defect: Over-Expanded or Blown Core	79
3.5.2	Core Defect: Core Crushing or Movement	79
3.5.3	Core Defect: Core-Splice Spacing Exceeding Limits	80
3.5.4	Core Defect: Incorrect or Variable Core Thickness	80
3.5.5	Core Defect: Core Degradation Due to Core Defect – Water Entrapment in Core	81
3.5.6	Core Defect: Incorrect Core Density	81
3.5.7	Core Defect: Misaligned Nodes or Unbonded Nodes in Core Cell	81
3.5.8	Core Defect: Mismatched Nodes or Corrugations	82
3.5.9	Core Defect: Corrosion	82
3.5.10	Facesheet Defect: Pillowing, Wrinkling, or Orange Peel	82
3.5.11	Facesheet Defect: Dents in Facesheet	83
3.5.12	Facesheet/Core Disbond	83
3.5.13	Defects in Adhesive Fillets	84

- 3.5.14 Edge-Closeout Defects 84
- 3.6 Defects by Location: Mixed-Mode Fiber and Matrix Defects 86
  - 3.6.1 Impact Damage with Fiber Breakage 86
  - 3.6.2 Bearing Damage 87
  - 3.6.3 Edge Cracking and Crushing 88
  - 3.6.4 Cuts, Scratches, and Gouges 89
  - 3.6.5 Composite Damage from Lightning Strikes 89
  - 3.6.6 Misdrilled Holes 90
  - 3.6.7 Mismatched Parts 90
  - 3.6.8 Incorrect Fiber Orientation or Missing Plies 91
  - 3.6.9 Galvanic Corrosion 91
  - 3.6.10 Resin Migration and Uneven Fiber Volume Fraction 92
  - 3.6.11 Residual Stresses and Dimensional Conformance 94
  - 3.6.12 Delaminations 96
  - 3.6.13 Composite Degradation Due to Excessive Temperature and Chemical Exposure 98
    - 3.6.13.1 Fibers 98
    - 3.6.13.2 Matrix 98
- 3.7 Defects by Location: Fastened and Bonded Joint Defects 98
  - 3.7.1 Fastened Joints 98
    - 3.7.1.1 Bearing Damage 99
    - 3.7.1.2 Hole Delamination/Fraying 99
    - 3.7.1.3 Hole Elongation or Out-of-Round Holes 99
    - 3.7.1.4 Fastener Seating 99
    - 3.7.1.5 Fastener Over-Torque 99
    - 3.7.1.6 Fastener Under-Torque 100
    - 3.7.1.7 Missing Fastener 100
    - 3.7.1.8 Porosity Near the Fastener 100
    - 3.7.1.9 Resin-Starved Bearing Surface 100
    - 3.7.1.10 Insufficient Edge Margins 100
    - 3.7.1.11 Tilted Hole 100
  - 3.7.2 Bonded Joints 100
    - 3.7.2.1 Poor Cure Due to Improper Material Chemistry: Mixing of Two-Part Resins or Material Past Shelf- or Out Life 103
    - 3.7.2.2 Incorrect Bondline Thickness, Scarf, or Overlap Length 103
    - 3.7.2.3 Zero-Volume Disbond or Long-Term Bond Failure Due to Contamination or Incorrect Surface Preparation 103
    - 3.7.2.4 Bondline Degradation Due to Moisture or Incorrect Pressure During Processing 103
    - 3.7.2.5 Bondline Degradation Due to Incorrect Heating Procedures 104
- 3.8 Future Directions 104
- References 104

<b>4</b>	<b>Inspection Methods</b>	<b>111</b>
4.1	Introduction	111
4.2	Mechanical Vibration NDT Methods	117
4.2.1	Low Frequency Methods	117
4.2.1.1	Tap Testing	117
4.2.1.2	Mechanical Impedance	117
4.2.1.3	Membrane Resonance	118
4.2.2	High Frequency Ultrasonic Methods	118
4.2.2.1	Pulse Echo and Thru-Transmission	118
4.2.2.2	Pulse Echo Ultrasonics	119
4.2.2.3	Through-Transmission Ultrasonics	119
4.2.2.4	Phased Array Ultrasonics	120
4.2.2.5	Ultrasonic Spectroscopy for Zero-Volume Disbonds	120
4.2.2.6	Ultrasonic Methods for Fiber Distortion	120
4.2.2.7	Guided Lamb Waves	122
4.2.2.8	Air-Coupled Ultrasonics	122
4.2.3	Acoustic Emission	123
4.3	Visual and Enhanced Visual Methods	125
4.3.1	Visual Inspections	125
4.3.2	Verification or Pressure Film	125
4.3.3	Leak Testing	126
4.4	Electromagnetic Radiation (X-Ray, Gamma, and Neutron)	126
4.4.1	Radiography	126
4.4.2	Computed Tomography	127
4.4.3	Compton Scattering	130
4.4.4	Neutron Tomography	131
4.5	Optical Methods	131
4.5.1	Shearography	131
4.5.2	Digital Image Correlation (DIC)	133
4.5.3	Hyperspectral Near Infrared Method for Resin Migration and Fiber Distortion	135
4.5.4	Laser Profilometers and Image Processing	136
4.6	Strain Measurement	137
4.7	Thermography	138
4.7.1	Active Thermography	139
4.7.1.1	Thermoelastic Stress Analysis	139
4.7.2	Passive Thermography	139
4.8	Destructive Methods	142
4.8.1	Physical Tests	142
4.8.2	Density and Porosity Measurements	144
4.8.3	Microscopy	145
4.9	NDT Standards	147
	References	147

<b>5</b>	<b>Effects of Defects – Design Values and Statistical Considerations</b>	<b>159</b>
5.1	Introduction	159
5.2	Effects on Laminate Properties	162
5.2.1	Cure Cycle Anomalies	162
5.2.1.1	Porosity	162
5.2.1.2	Nonuniformly Distributed Voids (Stratified Porosity)	163
5.2.1.3	Stratified Porosity or Delamination in L-Shaped Details	163
5.2.1.4	In-Plane Fiber Misalignment	164
5.2.1.5	Fiber Waviness (Out-of-Plane)	164
5.2.1.6	Waviness in Curved Parts	168
5.2.1.7	Ply Gaps and Overlaps	170
5.2.2	Cuts, Scratches, and Gouges	171
5.2.3	Edge Delaminations	172
5.2.4	Foreign Object Impact	172
5.3	Effects on Sandwich Composites Properties	174
5.3.1	Facesheet to Core Disbonding	174
5.3.2	Facesheet Pillowing	175
5.3.3	Node Disbonds	176
5.3.4	Core Splicing	176
5.4	Effects on Bolted Joint Properties	179
5.4.1	Delaminations at the Holes	180
5.4.2	Oversize Holes	182
5.4.3	Over-Torqued Fasteners	182
5.4.4	Porosity Near Fasteners	184
5.5	Effects on Bonded Joint Properties	184
5.5.1	Assessment of Defects in Design of Bonded Joints	185
5.6	Statistical Considerations	185
5.6.1	Mean versus Design Values	189
5.6.2	Simpson’s Paradox	189
5.6.3	Design of Experiments	189
5.7	Suggested Approach for Evaluation of Defects	191
5.8	Evaluation of Scaling and Multiple Defects	192
	References	194
<b>6</b>	<b>Selected Case Studies in Effects of Defects</b>	<b>201</b>
6.1	Introduction	201
6.2	Case Study 1: The Ohio Timber Road II Wind Turbine Failure Due to Wrinkles	201
6.2.1	Event	201
6.2.2	Background	201
6.2.3	Investigation	202
6.2.4	Lessons Learned	202

6.3	Case Study 2: Faulty Repairs of Sandwich Core Structure	203
6.3.1	Event	203
6.3.2	Lessons Learned	203
6.4	Case Study 3: Bonded Repair Failure	205
6.4.1	Event	205
6.4.2	Investigation	205
6.4.3	Lessons Learned	205
6.5	Case Study 4: Air Transat 961 Sandwich-Composite Failure	206
6.5.1	Event	206
6.5.2	Investigation	206
6.5.3	Lessons Learned	207
6.6	Case Study 5: Debonding Failure of a Sandwich-Composite Cryogenic Fuel Tank	208
6.6.1	Event	208
6.6.2	Investigation	208
6.6.3	Lessons Learned	208
	References	209

**Glossary** 211

**Index** 215