

Oliver Kastner

First Principles Modelling of Shape Memory Alloys

Molecular Dynamics Simulations

 Springer

Contents

| | | |
|----------|---|----|
| 1 | Preparations | 1 |
| 1.1 | An Introduction to Shape Memory Alloys | 1 |
| 1.1.1 | Thermo-Mechanical Phenomena | 1 |
| 1.1.2 | Martensitic Transformations | 3 |
| 1.1.3 | Microstructures | 4 |
| 1.1.4 | Scales | 6 |
| 1.2 | Crystallographic Theory | 9 |
| 1.3 | Thermodynamics | 11 |
| 1.3.1 | Phase Stability Criterion | 11 |
| 1.3.2 | Nucleation and Hysteresis | 18 |
| 1.3.3 | Dynamics of Atomic Assemblies | 21 |
| 1.3.4 | Statistical Thermodynamics | 23 |
| 1.4 | Engineering Models of SMA | 28 |
| | References | 29 |
| 2 | The Method of Molecular Dynamics Simulations | 35 |
| 2.1 | Interaction Models | 35 |
| 2.2 | Numerics | 37 |
| 2.2.1 | Accuracy Issues | 37 |
| 2.2.2 | Integration Schemes | 39 |
| 2.2.3 | Non-Dimensionalisation | 41 |
| 2.2.4 | Thermostats | 42 |
| 2.2.5 | Periodic Boundary Conditions | 45 |
| 2.2.6 | Parrinello–Rahman | 47 |
| 2.2.7 | Parallelisation | 49 |
| 2.2.8 | MD Simulation Computer Program | 52 |
| 2.3 | Post-Processing | 53 |
| | References | 55 |

| | | |
|----------|---|-----|
| 3 | 2D Model Material | 59 |
| 3.1 | The Model Material | 59 |
| 3.2 | Infinite and Perfect Single Crystals | 64 |
| 3.2.1 | Harmonic Limit: Linearised Equations of Motion | 64 |
| 3.2.2 | Phase Stability of 2D Lattices | 67 |
| 3.2.3 | Entropic Stabilisation of Austenite | 71 |
| 3.3 | Crystallographic Theory | 74 |
| 3.4 | Thermo-Mechanical Properties | 74 |
| 3.4.1 | Individual Crystallites | 74 |
| 3.4.2 | Chains of Crystallites | 77 |
| | References | 84 |
| 4 | Lattice Transformations in 2D Crystals | 87 |
| 4.1 | Temperature-Induced Transformations | 87 |
| 4.1.1 | Strip-Shaped Rectangles | 88 |
| 4.1.2 | Quad-Shaped Rectangles | 90 |
| 4.1.3 | Substrate Layers | 98 |
| 4.2 | Transformation Dynamics and Microstructure | 100 |
| 4.3 | Nucleation of Martensite | 102 |
| 4.3.1 | Simulation Setup | 104 |
| 4.3.2 | Simulation Result | 105 |
| 4.3.3 | Nucleation Centres | 108 |
| 4.3.4 | Frequency Analysis | 110 |
| 4.3.5 | Phase Space Analysis | 118 |
| 4.3.6 | Entropic Nucleation Barrier | 120 |
| 4.4 | Tensile Testing in the Pseudo-Elastic Regime | 121 |
| 4.4.1 | Simulation Procedure | 121 |
| 4.4.2 | Load Control Mode | 123 |
| 4.4.3 | Displacement Control Mode | 129 |
| 4.5 | Tensile Testing in the Pseudo-Plastic Regime | 134 |
| 4.6 | Transformation Cycles | 137 |
| 4.6.1 | Procedure | 137 |
| 4.6.2 | Reverse Transformation of the 160,000-Atom Quad | 139 |
| 4.6.3 | Cyclic Transformation Processes | 139 |
| 4.7 | Hysteresis and Functional Fatigue | 145 |
| 4.7.1 | Thermodynamic Hysteresis | 145 |
| 4.7.2 | Functional Fatigue | 146 |
| 4.7.3 | Predicted and Observed Hysteresis | 146 |
| | References | 148 |
| 5 | Lattice Transformations in 3D Crystals | 151 |
| 5.1 | 3D Lennard-Jones Crystals | 151 |
| 5.1.1 | Model Material | 151 |
| 5.1.2 | Procedure | 153 |
| 5.1.3 | Results | 154 |

| | |
|-------------------------------------|-----|
| 5.2 Zirconium Crystal | 157 |
| 5.2.1 Model | 157 |
| 5.2.2 Simulation Procedure. | 159 |
| 5.2.3 Results. | 160 |
| 5.3 Conclusions | 162 |
| References | 162 |
| 6 Conclusions | 165 |
| Reference | 168 |
| Index | 169 |