

Joshua Pelleg

Diffusion in Ceramics

 Springer

Contents

Part I Fundamentals of Diffusion

1	Macroscopic Diffusion	3
1.1	Fick's First Law	3
1.2	Fick's Second Law	4
1.3	Some Most Common Solutions for Eq. (1.5)	6
1.3.1	Thin-Film Solution	7
1.3.2	Short Bar	8
1.3.3	Diffusion in a Pair of Semi-infinite Solids (The Extended Initial Distribution of the Diffusant)	9
1.3.4	Diffusant Confined in a Region, $-h < x < +h$	10
1.3.5	Separation of Variables: A Method for Solving the Diffusion Equation	12
1.3.6	Diffusion Out of a Slab	13
	References.	14
	Further Reading	14
2	Microscopic (or Atomic) Diffusion	15
2.1	Random Motion of Atoms	15
2.2	Random Walk.	17
	References.	20
3	Defects in Materials	21
3.1	Schematic Illustration of Point Defects.	22
3.1.1	Vacancies	22
3.1.2	Interstitials	23
3.1.3	Point Defects of Mixed Character	23
3.1.4	Point Defects in a Crystal.	25

3.2	Thermodynamics of Vacancy Formation	26
3.2.1	Vacancy Generation	28
3.2.2	Quenched-In Vacancies	29
3.2.3	Defect Formation by Plastic Deformation	29
3.2.4	Production of Defects by Radiation	30
	Further Reading	30
4	Mechanism of Diffusion	31
4.1	Vacancy Mechanism	32
4.2	Direct Interstitial Mechanism	34
4.3	Interstitialcy Mechanism	38
	Further Reading	39
5	Self-diffusion, Solute Diffusion, Diffusion in Ionic Crystals and Correlation Effects	41
5.1	Self-diffusion in Oxides	42
5.2	Solute Diffusion in Very Dilute Solution	47
5.3	Diffusion and Conductivity of Ions	49
5.3.1	Ionic Conductivity	51
5.4	Binding Energy	57
5.5	Correlation Effect	58
5.6	Enhanced Diffusion	62
5.7	Isotope Effect	65
	Appendix 5.1: Kröger and Vink Relation	66
	References	68
	Further Reading	68
6	Interdiffusion	69
6.1	Darken's Equation	70
	References	73
	Further Reading	74
7	Diffusion in Grain Boundaries	75
7.1	Introduction	75
7.2	Self-diffusion	76
7.3	Solute (Impurity) Diffusion	77
7.4	Diffusion in Nanoceramics	78
	Appendix 7.1: Grain-Boundary Diffusion: Whipple-Le Claire Approach	82
	Appendix 7.2: Diffusion in Nanosized Crystals	84
	References	86
	Further Reading	86

8	Diffusion in Dislocations	87
8.1	Introduction	87
8.2	Self-diffusion	88
8.3	Solute (Impurity) Diffusion.	93
	References.	94
	Further Reading	94
9	Experimental Methods and Procedures	95
9.1	Introduction	95
9.2	Tracer Technique	96
9.3	SIMS Technique	100
9.4	Conductivity	101
	References.	103
	Further Reading	104
10	Empirical Rules	105
10.1	Diffusion Distance.	105
10.2	D and Melting Point	106
10.3	The Activation Energy Relation	106
10.4	The Enthalpy of Heat of Evaporation and the Activation Energy	107
10.5	D ₀ Evaluation	108
10.6	Effect of Impurity	108
	References.	109

Part II Diffusion in Ceramics (Experimental)

11	Diffusion in Alumina Single Crystals	113
11.1	Aluminum Self-diffusion in Single-Crystal Alumina (Corundum)	114
11.2	Oxygen Self-diffusion in Single-Crystal Alumina (Corundum)	118
11.3	Impurity (Solute) Diffusion in Corundum (Single-Crystal Alumina)	122
11.3.1	Chromium Diffusion in Sapphire.	122
11.3.2	Iron Diffusion in Sapphire	125
11.3.3	Titanium Diffusion in Sapphire	126
11.3.4	Cobalt Diffusion in Alumina.	129
11.3.5	Ytria Diffusion in Alumina	134
11.3.6	Silver Diffusion in Alumina	136
11.3.7	Copper Diffusion in Alumina	140

11.4	Self-diffusion in Polycrystalline Alumina	141
11.4.1	Introduction	141
11.4.2	Alumina Self-diffusion	142
11.4.3	Oxygen Self-diffusion in Alumina	143
11.5	Impurity (Solute) Diffusion in Polycrystalline Alumina	145
11.5.1	Yttrium Diffusion in Polycrystalline Alumina	145
11.5.2	Silver Diffusion in Polycrystalline Alumina	146
11.6	Grain Boundary Diffusion in Alumina	148
11.6.1	Introduction	148
11.6.2	Oxygen Grain-Boundary Diffusion in Alumina	148
11.6.3	Aluminum Grain-Boundary Diffusion in Alumina	153
11.7	Impurity (Solute) Diffusion in Alumina Grain Boundaries	154
11.7.1	Chromium Diffusion	154
11.7.2	Nickel Diffusion	157
11.7.3	Ag Diffusion	158
11.8	Dislocation Diffusion in Alumina	160
11.8.1	Introduction	160
11.8.2	Diffusion of Oxygen in Dislocations of Alumina	162
11.8.3	Diffusion of Aluminum in Dislocations of Alumina	166
11.9	Impurity (Solute) Diffusion in Dislocations of Alumina	167
11.9.1	Cr Diffusion in Dislocations	167
11.9.2	Titanium Diffusion in Dislocations	171
11.9.3	Nickel Diffusion in Dislocations	171
11.10	Summary of Diffusion Data in Al_2O_3	174
	References	176
	Further Reading	176
12	Diffusion in Silicon Carbide (Carborundum)	179
12.1	Self-diffusion of Si in Single-Crystal α -SiC	180
12.2	Self-diffusion of C in Single-Crystal α -SiC	181
12.3	Effect of Doping on Self-diffusion	183
12.4	Impurity (Solute) Diffusion in SiC Single Crystals	187
12.4.1	Al Diffusion into 4H-SiC Crystals	187
12.4.2	B Diffusion in SiC	187
12.4.3	Ga Diffusion in SiC	190
12.4.4	Be Diffusion in SiC	193
12.4.5	N Diffusion in SiC	196
12.4.6	P-Diffusion in SiC	199
12.5	Self-diffusion in Polycrystalline SiC	199
12.5.1	Introduction	199
12.5.2	Si Self-diffusion in Polycrystalline SiC	200

12.6	Impurity (Solute) Diffusion Polycrystalline SiC	205
12.6.1	Fe Diffusion in Polycrystalline SiC	205
12.6.2	Cr Diffusion in Polycrystalline SiC	208
12.6.3	Co Diffusion in Polycrystalline SiC	209
12.6.4	Be, Mg, Na and F Radiotracers Diffusion in Polycrystalline SiC	210
12.6.5	Ag Diffusion in Polycrystalline SiC	215
12.6.6	Diffusion of Fission Products in Pyrolytic SiC	217
12.7	Self-diffusion in Grain Boundaries of SiC	220
12.7.1	Introduction	220
12.7.2	Self-diffusion of Si in SiC Grain Boundaries.	221
12.7.3	Self-diffusion of C in SiC Grain Boundaries.	221
12.8	Impurity (Solute) Diffusion in SiC Grain Boundaries	224
12.8.1	Al Diffusion	224
12.8.2	B Diffusion.	225
12.9	Dislocation Diffusion in SiC	228
12.9.1	Diffusion of Fe, Cr and Co in Dislocations.	228
12.10	Summary of Diffusion Data in SiC	233
	References.	235
	Further Reading	236
13	Diffusion in MgO (Magnesia or Periclase)	237
13.1	Introduction	237
13.2	Self-diffusion of Mg in Single Crystal MgO	238
13.3	Oxygen Self-diffusion in Single-Crystal MgO	239
13.4	Impurity (Solute) Diffusion in MgO Single Crystals	243
13.4.1	Introduction	243
13.4.2	Be Diffusion in Single-Crystal MgO	243
13.4.3	Ca Diffusion in Single-Crystal MgO	244
13.4.4	Sr Diffusion in Single-Crystal MgO	247
13.4.5	Ba Diffusion in Single-Crystal MgO	248
13.4.6	Li and Na Diffusion in Single-Crystalline MgO.	253
13.4.7	Zn Diffusion in Single-Crystalline MgO	256
13.4.8	Cd Diffusion in Single-Crystalline MgO	256
13.4.9	B Diffusion in Single-Crystalline MgO	257
13.4.10	Al Diffusion in Single-Crystalline MgO	258
13.4.11	Ga Diffusion in Single-Crystalline MgO	260
13.4.12	Diffusion of Transition Elements, Co, Ni, Fe and Mn in Single-Crystalline MgO	261
13.4.13	Y Diffusion in Single-Crystal MgO	263
13.4.14	Pd Diffusion in Single-Crystal MgO	266
13.4.15	C Diffusion in Single-Crystal MgO	267
13.4.16	Si Diffusion in Single-Crystal MgO	271

13.4.17	Ge Diffusion in Single-Crystal MgO	273
13.4.18	P Diffusion in Single-Crystal MgO	274
13.5	Self-diffusion in Polycrystalline MgO	275
13.5.1	Introduction	275
13.5.2	Oxygen Self-diffusion	275
13.6	Grain-Boundary Diffusion in MgO	278
13.6.1	Introduction	278
13.6.2	O Self-diffusion in MgO Grain Boundaries	278
13.7	Impurity (Solute) Diffusion in MgO Grain Boundaries	283
13.7.1	Ni Diffusion in MgO Grain Boundaries	283
13.8	Dislocation Diffusion in MgO	286
13.8.1	Introduction	286
13.8.2	Mg Diffusion in Dislocations	287
13.8.3	O Diffusion in Dislocations	290
13.9	Impurity Diffusion in Dislocations	291
13.9.1	Ca Diffusion in Dislocations	291
13.9.2	Sr Diffusion in Dislocations	291
13.9.3	Ba Diffusion in Dislocations	291
13.9.4	Li and Na Diffusion in Dislocations	294
13.9.5	Si and P Diffusion in Dislocations	295
13.10	Summary of the Chapter and Diffusion Data in MgO	295
	References	298
	Further Reading	298
14	Diffusion in ZrO₂ (Zirconia)	301
14.1	Introduction	301
14.2	Zr (Zirconium) Self-diffusion in Single-Crystal (SC) ZrO ₂	302
14.3	O (Oxygen) Self-diffusion in Single-Crystal (SC) ZrO ₂	303
14.4	Impurity (Solute) Diffusion in SC ZrO ₂	306
14.4.1	Diffusion of Ca (Calcium) in Zirconia	306
14.4.2	Diffusion of Sc (Scandium) in Single-Crystal (SC) Zirconia	307
14.4.3	Diffusion of Y in SC Zirconia	308
14.4.4	Diffusion of Lanthanides in SC ZrO ₂	309
14.4.5	Nb (Niobium) Diffusion	318
14.4.6	Diffusion of Transition VIII Group Metals	322
14.4.7	C (Carbon) Diffusion	327
14.4.8	N (Nitrogen) Diffusion	329
14.5	Diffusion in ZrO ₂ (Zirconia) Polycrystals	331
14.5.1	Introduction	331
14.5.2	O Diffusion in Monoclinic Zirconia	331
14.5.3	O Diffusion in Tetragonal Zirconia	333
14.6	Effect of Pressure on O Diffusion	336
14.7	Zr Self-diffusion in Polycrystalline ZrO ₂	340
14.7.1	Introduction	340

14.8	Scandia-Stabilized Zirconia.	341
14.9	Calcia-Stabilized Zirconia.	342
14.10	Ytria-Stabilized ZrO_2	343
14.11	Impurity (Solute) Diffusion in Polycrystalline ZrO_2	345
14.11.1	Ti (Titanium) Diffusion	345
14.11.2	Hf (Hafnium) Diffusion	346
14.11.3	H (Hydrogen) Diffusion	350
14.11.4	Cs (Cesium) Diffusion	352
14.11.5	Mg (Magnesium) Diffusion	355
14.11.6	Ca (Calcium) Diffusion	358
14.11.7	Sr (Strontium) Diffusion.	360
14.11.8	Y (Yttrium) Diffusion	361
14.11.9	Lanthanide Diffusion	363
14.11.10	Nb (Niobium) Diffusion.	369
14.11.11	Mn (Manganese) Diffusion.	370
14.11.12	Diffusion in the Transition VIII A Group Metals	370
14.11.13	Al (Aluminum) Diffusion	373
14.11.14	He (Helium) Diffusion	376
14.12	Grain-Boundary Diffusion in Zirconia	380
14.12.1	Zr Self-diffusion	380
14.12.2	O Self-diffusion.	383
14.13	Impurity Diffusion in Grain Boundaries	384
14.13.1	Ti (Titanium) Diffusion	384
14.13.2	Hf (Hafnium) Diffusion	386
14.13.3	Mg (Magnesium) Diffusion.	390
14.13.4	Ca (Calcium) Diffusion	391
14.13.5	Y (Yttrium) Diffusion	392
14.13.6	Diffusion in Lanthanides	393
14.13.7	Nb Diffusion.	395
14.13.8	Fe Diffusion	396
14.13.9	Al Diffusion	397
14.14	Diffusion in Zr Dislocations	400
14.14.1	Introduction	400
14.14.2	Self-diffusion of O.	400
14.15	Impurity Diffusion in Dislocations.	402
14.15.1	Y Diffusion	402
14.16	Concluding Comments for This Chapter.	404
14.17	Summary of Diffusion Data in Zirconia	404
	References.	410
	Further Reading	411

15	Diffusion in Si_3N_4	413
15.1	Introduction	413
15.2	Self-diffusion in Si_3N_4 Single Crystal	414
15.3	Nitrogen Self-diffusion in Single-Crystal Si_3N_4	415
15.4	Diffusion in Polycrystalline Si_3N_4	416
15.4.1	Introduction	416
15.5	Si Self-diffusion in Polycrystalline Si_3N_4	416
15.6	N Self-diffusion in Polycrystalline Si_3N_4	419
15.7	Diffusion in Amorphous Si_3N_4	421
15.7.1	Introduction	421
15.7.2	N Self-diffusion in Amorphous Si_3N_4	421
15.8	Impurity (Solute) Diffusion in Single, Polycrystalline and Amorphous Si_3N_4	422
15.8.1	Ge (Germanium) Diffusion	422
15.8.2	Ti Diffusion	423
15.8.3	P (Phosphorus) Diffusion (Amorphous Si_3N_4)	427
15.8.4	H Diffusion (Amorphous Si_3N_4)	429
15.8.5	Au (Gold) Diffusion (Amorphous Si_3N_4)	433
15.8.6	Al Diffusion	434
15.8.7	Ga Diffusion	436
15.8.8	Ni Diffusion	437
15.9	Grain-Boundary Diffusion in Si_3N_4	439
15.10	Diffusion in Dislocations	439
15.11	Summary of the Chapter and Diffusion Data on Si_3N_4	440
	References	443
	Further Reading	443
Index	445