

# Design of Experiments for Engineers and Scientists

Jiju Antony

**B**UTTERWORTH  
**H**EINEMANN

AMSTERDAM BOSTON HEIDELBERG LONDON NEW YORK OXFORD  
PARIS SAN DIEGO SAN FRANCISCO SINGAPORE SYDNEY TOKYO

---

# Contents

<i>Preface</i>	xi
<i>Acknowledgements</i>	xii
<b>1 Introduction to industrial experimentation</b>	<b>1</b>
1.1 Introduction	1
1.2 Some fundamental and practical issues in industrial experimentation	3
1.3 Summary	5
Exercises	5
References	5
<b>2 Fundamentals of Design of Experiments</b>	<b>6</b>
2.1 Introduction	6
2.2 Basic principles of Design of Experiments	7
2.2.1 Randomization	8
2.2.2 Replication	9
2.2.3 Blocking	10
2.3 Degrees of freedom	10
2.4 Confounding	11
2.5 Design resolution	12
2.6 Metrology considerations for industrial designed experiments	12
2.6.1 Measurement system capability	13
2.6.2 Some tips for the development of a measurement system	14
2.7 Selection of quality characteristics for industrial experiments	15
Exercises	15
References	16
<b>3 Understanding key interactions in processes</b>	<b>17</b>
3.1 Introduction	17
3.2 Alternative method for calculating the two order interaction effect	20
3.3 Synergistic interaction vs antagonistic interaction	22
3.4 Scenario 1	23

---

3.5	Scenario 2	25
3.6	Summary	27
	Exercises	27
	References	28
<b>4</b>	<b>A systematic methodology for Design of Experiments</b>	<b>29</b>
4.1	Introduction	29
4.2	Barriers in the successful application of DOE	29
4.3	A practical methodology for DOE	31
4.3.1	Planning phase	31
4.3.2	Designing phase	33
4.3.3	Conducting phase	33
4.3.4	Analysing phase	34
4.4	Analytical tools of DOE	34
4.4.1	Main effects plot	34
4.4.2	Interactions plots	35
4.4.3	Cube plots	36
4.4.4	Pareto plot of factor effects	36
4.4.5	Normal Probability Plot of factor effects	36
4.4.6	Normal Probability Plot of residuals	37
4.4.7	Response surface plots and regression models	38
4.5	Model building for predicting response function	40
4.6	Confidence interval for the mean response	41
4.7	Summary	42
	Exercises	42
	References	43
<b>5</b>	<b>Screening designs</b>	<b>44</b>
5.1	Introduction	44
5.2	Geometric and non-geometric P-B designs	44
5.3	Summary	52
	Exercises	53
	References	53
<b>6</b>	<b>Full factorial designs</b>	<b>54</b>
6.1	Introduction	54
6.2	Example of a $2^2$ full factorial design	54
6.2.1	Objective 1: Determination of main/interaction effects which influence mean plating thickness	55
6.2.2	Objective 2: Determination of main/interaction effects which influence variability in plating thickness	57
6.2.3	Objective 4: How to achieve a target plating thickness of 120 units?	58
6.3	Example of a $2^3$ full factorial design	60
6.3.1	Objective 1: To identify the significant main/interaction effects which affect the process yield	61

6.3.2	Objective 2: To identify the significant main/interaction effects which affect the variability in process yield	63
6.3.3	Objective 3: What is the optimal process condition?	64
6.4	Example of a $2^4$ full factorial design	65
6.4.1	Objective 1: Which of the main/interaction effects affect mean crack length?	66
6.4.2	Objective 2: Which of the main/interaction effects affect variability in crack length?	66
6.4.3	Objective 3: What is the optimal process condition to minimize mean crack length?	69
6.5	Summary	70
	Exercises	71
	References	72
<b>7</b>	<b>Fractional factorial designs</b>	<b>73</b>
7.1	Introduction	73
7.2	Construction of half-fractional factorial designs	73
7.3	Example of a $2^{(7-4)}$ factorial design	76
7.4	An application of 2-level fractional factorial design	80
7.5	Example of a $2^{(5-1)}$ factorial design	85
7.5.1	Objective 1: To identify the factors which influence the mean free height	86
7.5.2	Objective 2: To identify the factors which affect variability in the free height of leaf springs	87
7.5.3	How do we select the optimal factor settings to minimize variability in free height?	89
7.6	Summary	90
	Exercises	90
	References	92
<b>8</b>	<b>Some useful and practical tips for making your industrial experiments successful</b>	<b>93</b>
8.1	Introduction	93
8.1.1	Get a clear understanding of the problem	94
8.1.2	Project selection	94
8.1.3	Conduct exhaustive and detailed brainstorming session	95
8.1.4	Teamwork and selection of a team for experimentation	96
8.1.5	Select the continuous measurable quality characteristics or responses for the experiment	96
8.1.6	Choice of an appropriate Experimental Design	98
8.1.7	Iterative experimentation	98
8.1.8	Randomize the experimental trial order	99

8.1.9	Replicate to dampen the effect of noise or uncontrolled variation	99
8.1.10	Improve the efficiency of experimentation using blocking strategy	101
8.1.11	Understanding the confounding pattern of factor effects	101
8.1.12	Perform confirmatory runs/experiments	102
8.2	Summary	102
	Exercises	103
	References	103
<b>9</b>	<b>Case studies</b>	<b>105</b>
9.1	Introduction	105
9.2	Case studies	105
9.2.1	Optimization of a radiographic quality welding of cast iron	105
9.2.2	Reducing process variability using Experimental Design technique objective of the experiment	110
9.2.3	Slashing scrap rate using fractional factorial experiments	114
9.2.4	Optimizing the time of flight of a paper helicopter	117
9.2.5	Optimizing a wire bonding process using Design of Experiments	123
9.2.6	Training for Design of Experiments using a catapult	127
9.2.7	Optimization of core tube life using designed experiments	132
9.2.8	Optimization of a spot welding process using Design of Experiments	141
9.3	Summary	147
	References	148
	<i>Index</i>	149