

# Product Design for Manufacture and Assembly

## Third Edition

**Geoffrey Boothroyd**  
**Peter Dewhurst**  
**Winston A. Knight**



**CRC Press**

Taylor & Francis Group

Boca Raton London New York

---

CRC Press is an imprint of the  
Taylor & Francis Group, an **informa** business

---

# Contents

---

Preface.....	xix
Preface to the Second Edition.....	xxi
Preface to the First Edition.....	xxiii
Authors.....	xxv
Nomenclature.....	xxvii
<b>1. Introduction.....</b>	<b>1</b>
1.1 What Is Design for Manufacture and Assembly?.....	1
1.2 History.....	1
1.3 Implementation of Design for Assembly.....	4
1.4 Design for Manufacture.....	5
1.5 Producibility Guidelines.....	5
1.6 How Does DFMA Work?.....	8
1.7 Falsely Claimed Reasons for Not Implementing DFMA.....	15
1.7.1 No Time.....	15
1.7.2 Not Invented Here.....	15
1.7.3 Ugly Baby Syndrome.....	15
1.7.4 Low Assembly Costs.....	15
1.7.5 Low Volume.....	17
1.7.6 We Have Been Doing It for Years.....	17
1.7.7 It Is Only Value Analysis.....	17
1.7.8 DFMA Is Only One among Many Techniques.....	17
1.7.9 DFMA Leads to Products that are more Difficult to Service.....	18
1.7.10 I Prefer Design Rules.....	18
1.7.11 I Refuse to Use DFMA.....	18
1.8 What Are the Advantages of Applying DFMA during Product Design?.....	19
1.9 Overall Impact of DFMA on U.S. Industry.....	22
1.10 Conclusions.....	23
References.....	26
<b>2. Selection of Materials and Processes.....</b>	<b>29</b>
2.1 Introduction.....	29
2.2 General Requirements for Early Materials and Process Selection.....	29
2.2.1 Relationship to Process and Operations Planning.....	31
2.3 Selection of Manufacturing Processes.....	31
2.4 Process Capabilities.....	34
2.4.1 General Shape Attributes.....	34
2.4.2 DFA Compatibility Attributes.....	35
2.5 Selection of Materials.....	35
2.5.1 Grouping of Materials into Process Compatible Classes.....	35
2.5.2 Material Selection by Membership Function Modification.....	41
2.5.3 Material Selection by Dimensionless Ranking.....	43
2.6 Primary Process/Material Selection.....	52
2.7 Systematic Selection of Processes and Materials.....	57

2.7.1	Computer-Based Primary Process/Material Selection .....	57
2.7.2	Expert Processing Sequence Selector .....	57
2.7.3	Economic Ranking of Processes .....	61
References	.....	70
<b>3.</b>	<b>Product Design for Manual Assembly .....</b>	<b>73</b>
3.1	Introduction .....	73
3.2	General Design Guidelines for Manual Assembly .....	74
3.2.1	Design Guidelines for Part Handling .....	74
3.2.2	Design Guidelines for Insertion and Fastening .....	74
3.3	Development of the Systematic Design for Assembly Methodology .....	79
3.4	Assembly Efficiency .....	81
3.5	Classification Systems .....	82
3.6	Effect of Part Symmetry on Handling Time .....	85
3.7	Effect of Part Thickness and Size on Handling Time .....	88
3.8	Effect of Weight on Handling Time .....	89
3.9	Parts Requiring Two Hands for Manipulation .....	90
3.10	Effects of Combinations of Factors .....	90
3.11	Effect of Symmetry for Parts That Severely Nest or Tangle and May Require Tweezers for Grasping and Manipulation .....	90
3.12	Effect of Chamfer Design on Insertion Operations .....	91
3.13	Estimation of Insertion Time .....	94
3.14	Avoiding Jams during Assembly .....	95
3.15	Reducing Disc-Assembly Problems .....	97
3.16	Effects of Obstructed Access and Restricted Vision on Insertion of Threaded Fasteners of Various Designs .....	98
3.17	Effects of Obstructed Access and Restricted Vision on Pop-Riveting Operations .....	99
3.18	Effects of Holding Down .....	100
3.19	Manual Assembly Database and Design Data Sheets .....	103
3.20	Application of the DFA Methodology .....	104
3.20.1	Results of the Analysis .....	107
3.21	Further Design Guidelines .....	110
3.22	Large Assemblies .....	113
3.23	Types of Manual Assembly Methods .....	114
3.24	Effect of Assembly Layout on Acquisition Times .....	118
3.25	Assembly Quality .....	121
3.26	Applying Learning Curves to the DFA Times .....	123
References	.....	131
<b>4.</b>	<b>Electrical Connections and Wire Harness Assembly .....</b>	<b>133</b>
4.1	Introduction .....	133
4.2	Wire or Cable Harness Assembly .....	135
4.3	Types of Electrical Connections .....	138
4.3.1	Solder Connections .....	139
4.3.2	Low-Pressure Connections .....	139
4.3.3	High-Pressure Connections .....	141
4.4	Types of Wires and Cables .....	143
4.5	Preparation and Assembly Times .....	144

4.5.1	Preparation.....	144
4.5.2	Assembly and Installation.....	150
4.5.3	Securing.....	155
4.5.4	Attachment.....	158
4.6	Analysis Method.....	162
4.6.1	Procedure.....	163
4.6.2	Case Study.....	165
	References.....	184
<b>5.</b>	<b>Design for High-Speed Automatic Assembly and Robot Assembly.....</b>	<b>185</b>
5.1	Introduction.....	185
5.2	Design of Parts for High-Speed Feeding and Orienting.....	186
5.3	Example.....	189
5.4	Additional Feeding Difficulties.....	193
5.5	High-Speed Automatic Insertion.....	193
5.6	Example.....	197
5.7	Analysis of an Assembly.....	198
5.8	General Rules for Product Design for Automation.....	198
5.9	Design of Parts for Feeding and Orienting.....	203
5.10	Summary of Design Rules for High-Speed Automatic Assembly.....	206
5.10.1	Rules for Product Design.....	206
5.10.2	Rules for the Design of Parts.....	206
5.11	Product Design for Robot Assembly.....	206
5.11.1	Summary of Design Rules for Robot Assembly.....	212
	References.....	218
<b>6.</b>	<b>Printed Circuit Board Design for Manufacture and Assembly.....</b>	<b>219</b>
6.1	Introduction.....	219
6.2	Design Sequence for Printed Circuit Boards.....	219
6.3	Types of Printed Circuit Boards.....	220
6.3.1	Number of Sides.....	220
6.3.2	Number of Layers.....	221
6.3.3	Board Materials.....	221
6.3.4	Device Types.....	222
6.3.5	Copper Weight.....	222
6.4	Bare Board Manufacture.....	222
6.4.1	Basic Bare Board Costs.....	223
6.4.2	Number of Boards per Panel.....	225
6.4.3	Hole Drilling.....	226
6.4.4	Optional Bare Board Processes.....	226
6.4.5	Bare Board Testing.....	227
6.5	Terminology.....	227
6.6	Assembly of Printed Circuit Boards.....	228
6.6.1	Assembly Operations for Through-Hole Printed Circuit Boards.....	229
6.6.1.1	Automatic Dual Inline Package Insertion.....	230
6.6.1.2	Automatic Axial (VCD) Insertion.....	232
6.6.1.3	Automatic Single Inline Package Insertion.....	234
6.6.1.4	Automatic Radial Component Insertion.....	234
6.6.1.5	Semiautomatic Insertion.....	235

6.6.1.6	Manual Insertion.....	235
6.6.1.7	Robot Insertion.....	236
6.6.1.8	Inspection and Rework.....	236
6.6.2	Assembly of Surface-Mounted Devices.....	236
6.6.3	Soldering Processes.....	238
6.6.3.1	Wave Soldering.....	238
6.6.3.2	Reflow Soldering.....	238
6.6.4	Other Assembly Processes.....	239
6.6.4.1	Cleaning.....	239
6.6.4.2	Rework.....	239
6.6.4.3	Board Testing.....	240
6.6.5	Assembly Sequences for Printed Circuit Boards.....	240
6.7	Estimation of PCB Assembly Costs.....	242
6.7.1	Component Insertion Costs.....	243
6.7.1.1	Insertion Cost.....	244
6.7.1.2	Setup Cost.....	246
6.7.1.3	Rework Cost.....	247
6.7.1.4	Programming Cost.....	247
6.7.2	Worksheet for Printed Circuit Board Assembly Costs.....	248
6.7.3	Example.....	248
6.8	Case Studies in PCB Assembly.....	250
6.8.1	Measuring Instrument Connector Board.....	250
6.8.2	Power Supply.....	254
6.9	Glossary of Terms.....	256
	References.....	260
<b>7.</b>	<b>Design for Machining.....</b>	<b>261</b>
7.1	Introduction.....	261
7.2	Machining Using Single-Point Cutting Tools.....	261
7.3	Machining Using Multipoint Tools.....	266
7.4	Machining Using Abrasive Wheels.....	275
7.5	Standardization.....	281
7.6	Choice of Work Material.....	282
7.7	Shape of Work Material.....	284
7.8	Machining Basic Component Shapes.....	284
7.8.1	Disc-Shaped Rotational Components ( $L/D \leq 0.5$ ).....	284
7.8.2	Short, Cylindrical Components ( $0.5 < L/D < 3$ ).....	288
7.8.3	Long, Cylindrical Rotational Components ( $L/D \geq 3$ ).....	288
7.8.4	Nonrotational Components ( $A/B \leq 3, A/C \geq 4$ ).....	291
7.8.5	Long, Nonrotational Components ( $A/B > 3$ ).....	293
7.8.6	Cubic, Nonrotational Components ( $A/B < 3, A/C < 4$ ).....	293
7.9	Assembly of Components.....	296
7.10	Accuracy and Surface Finish.....	297
7.11	Summary of Design Guidelines.....	300
7.12	Cost Estimating for Machined Components.....	301
7.12.1	Material Cost.....	302
7.12.2	Machine Loading and Unloading.....	303
7.12.3	Other Nonproductive Costs.....	303

7.12.4	Handling between Machines .....	303
7.12.5	Material Type.....	305
7.12.6	Machining Costs .....	305
7.12.7	Tool Replacement Costs .....	307
7.12.8	Machining Data .....	308
7.12.9	Rough Grinding.....	310
7.12.10	Finish Grinding.....	313
7.12.11	Allowance for Grinding Wheel Wear .....	313
7.12.12	Allowance for Spark-Out .....	315
7.12.13	Examples .....	315
7.12.14	Machining Cost Estimating Worksheet.....	317
7.12.15	Approximate Cost Models for Machined Components .....	321
	References .....	329
<b>8.</b>	<b>Design for Injection Molding .....</b>	<b>331</b>
8.1	Introduction .....	331
8.2	Injection Molding Materials .....	331
8.3	Molding Cycle.....	332
8.3.1	Injection or Filling Stage .....	333
8.3.2	Cooling or Freezing Stage.....	334
8.3.3	Ejection and Resetting Stage .....	334
8.4	Injection Molding Systems .....	334
8.4.1	Injection Unit .....	335
8.4.2	Clamp Unit.....	335
8.5	Injection Molds .....	336
8.5.1	Mold Construction and Operation.....	336
8.5.2	Mold Types .....	338
8.5.3	Sprue, Runner, and Gates .....	340
8.6	Molding Machine Size.....	340
8.7	Molding Cycle Time.....	343
8.7.1	Injection Time.....	343
8.7.2	Cooling Time .....	344
8.7.3	Mold Resetting .....	347
8.8	Mold Cost Estimation .....	349
8.8.1	Mold Base Costs .....	349
8.8.2	Cavity and Core Manufacturing Costs.....	351
8.9	Mold Cost Point System .....	357
8.10	Estimation of the Optimum Number of Cavities.....	360
8.11	Design Example.....	363
8.12	Insert Molding.....	364
8.13	Design Guidelines.....	365
8.14	Assembly Techniques .....	366
	References .....	372
<b>9.</b>	<b>Design for Sheet Metalworking .....</b>	<b>375</b>
9.1	Introduction .....	375
9.2	Dedicated Dies and Pressworking .....	376
9.2.1	Individual Dies for Profile Shearing .....	377

9.2.2	Cost of Individual Shearing Dies .....	381
9.2.3	Individual Dies for Piercing Operations .....	387
9.2.4	Individual Dies for Bending Operations.....	389
9.2.5	Individual Dies for Deep Drawing .....	392
9.2.6	Miscellaneous Features.....	398
9.2.7	Progressive Dies.....	399
9.3	Press Selection .....	400
9.3.1	Cycle Times.....	405
9.4	Turret Pressworking .....	407
9.5	Press Brake Operations .....	410
9.6	Design Rules .....	413
	References .....	421
<b>10.</b>	<b>Design for Die Casting .....</b>	<b>423</b>
10.1	Introduction .....	423
10.2	Die-Casting Alloys.....	423
10.3	Die-Casting Cycle .....	425
10.4	Die-Casting Machines .....	425
10.4.1	Die-Mounting and Clamping Systems .....	425
10.4.2	Metal-Pumping and Injection Systems.....	426
10.4.3	Hot-Chamber Machines.....	426
10.4.4	Cold-Chamber Machines.....	427
10.5	Die-Casting Dies .....	428
10.5.1	Trimming Dies .....	429
10.6	Finishing.....	429
10.7	Auxiliary Equipment for Automation .....	431
10.8	Determination of the Optimum Number of Cavities.....	431
10.9	Determination of Appropriate Machine Size .....	436
10.9.1	Required Machine Clamp Force.....	436
10.9.2	Shot Volume and Material Cost per Part.....	438
10.9.3	Dimensional Machine Constraints .....	439
10.10	Die Casting Cycle Time Estimation.....	441
10.10.1	Ladling of Molten Metal .....	441
10.10.2	Metal Injection.....	441
10.10.3	Metal Cooling.....	442
10.10.4	Part Extraction and Die Lubrication .....	446
10.10.5	Trimming Cycle Time .....	448
10.11	Die Cost Estimation .....	449
10.11.1	Die Set Costs .....	449
10.11.2	Cavity and Core Costs.....	450
10.11.3	Trim Die Costs.....	451
10.12	Assembly Techniques.....	453
10.13	Design Principles .....	455
	References .....	458
<b>11.</b>	<b>Design for Powder Metal Processing .....</b>	<b>461</b>
11.1	Introduction .....	461
11.2	Main Stages in the Powder Metallurgy Process .....	462
11.2.1	Mixing .....	463

11.2.2	Compaction.....	463
11.2.3	Sintering.....	464
11.3	Secondary Manufacturing Stages.....	464
11.3.1	Repressing and Resintering.....	464
11.3.2	Sizing and Coining.....	464
11.3.3	Infiltration.....	464
11.3.4	Impregnation.....	465
11.3.5	Resin Impregnation.....	465
11.3.6	Heat Treatment.....	466
11.3.7	Machining.....	466
11.3.8	Tumbling and Deburring.....	466
11.3.9	Plating and Other Surface Treatments.....	466
11.3.10	Steam Treating.....	466
11.3.11	Assembly Processes.....	466
11.4	Compaction Characteristics of Powders.....	467
11.4.1	Powder Compaction Mechanics.....	468
11.4.2	Compression Characteristics of Metal Powders.....	470
11.4.3	Powder Compression Ratio.....	473
11.5	Tooling for Powder Compaction.....	473
11.5.1	Compaction Dies.....	474
11.5.2	Punches for Compaction.....	475
11.5.3	Core Rods for Through Holes.....	475
11.5.4	Die Accessories.....	476
11.6	Presses for Powder Compaction.....	476
11.6.1	Factors in Choosing the Appropriate Press.....	476
11.6.1.1	Punch Motions.....	476
11.6.1.2	Load Required.....	477
11.6.1.3	Fill Height.....	477
11.6.1.4	Ejection Stroke.....	478
11.6.1.5	Maximum Die Diameter.....	478
11.6.2	Presses for Coining, Sizing, and Repressing.....	478
11.7	Form of Powder Metal Parts.....	479
11.7.1	Profile Complexity.....	480
11.8	Sintering Equipment Characteristics.....	481
11.8.1	Sintering Equipment.....	481
11.8.1.1	Continuous-Flow Furnaces.....	482
11.8.1.2	Batch Furnaces.....	484
11.9	Materials for Powder Metal Processing.....	484
11.10	Contributions to Basic Powder Metallurgy Manufacturing Costs.....	486
11.10.1	Material Costs.....	486
11.10.2	Compacting Costs.....	492
11.10.2.1	Press Selection.....	492
11.10.2.2	Setup Cost.....	494
11.10.3	Compaction Tooling Costs.....	495
11.10.3.1	Initial Tooling Costs.....	495
11.10.3.2	Tool Material Costs.....	495
11.10.3.3	Tool Manufacturing Costs.....	497
11.10.3.4	Dies.....	497
11.10.3.5	Punches.....	498



11.10.3.6	Core Rods .....	500
11.10.3.7	Total Tool Manufacturing Costs .....	501
11.10.4	Tool Accessory Costs .....	501
11.10.5	Tool Replacement Costs .....	502
11.10.6	Validation of the Tool Cost-Estimating Procedure.....	503
11.10.7	Sintering Costs .....	503
11.10.7.1	Continuous-Flow Furnaces.....	504
11.10.7.2	Batch Furnaces.....	505
11.10.8	Repressing, Coining, and Sizing .....	506
11.11	Modifications for Infiltrated Materials .....	506
11.11.1	Material Costs.....	506
11.11.2	Compaction Costs .....	507
11.11.3	Sintering Costs .....	507
11.12	Impregnation, Heat Treatment, Tumbling, Steam Treatment, and Other Surface Treatments .....	507
11.12.1	Processing Costs .....	507
11.12.2	Additional Material Costs .....	507
11.12.2.1	Self-Lubricating Bearing Materials.....	508
11.12.2.2	Materials Impregnated with Oil or Polymer.....	508
11.13	Some Design Guidelines for Powder Metal Parts .....	509
11.14	Powder Injection Molding .....	510
11.14.1	Feedstock Preparation and Pelletization .....	511
11.14.2	Molding .....	512
11.14.3	Debinding .....	512
11.14.4	Sintering .....	514
11.14.5	Secondary Operations .....	515
11.14.6	Feedstock Characteristics .....	515
11.14.7	Material Costs.....	519
11.14.8	Mold Cavity Geometry .....	521
11.14.9	Molding Costs .....	521
References	.....	525
<b>12.</b>	<b>Design for Sand Casting .....</b>	<b>527</b>
12.1	Introduction .....	527
12.2	Sand Casting Alloys .....	528
12.3	Basic Characteristics and Mold Preparation .....	529
12.3.1	Sand Preparation.....	529
12.3.2	Gating System.....	529
12.3.3	Mold Risers and Chills.....	530
12.3.4	Pattern Types .....	531
12.3.5	Sand Compaction Methods .....	532
12.4	Sand Cores .....	533
12.5	Melting and Pouring of Metal.....	533
12.6	Cleaning of Castings .....	534
12.7	Cost Estimating .....	535
12.7.1	Metal Cost .....	535
12.7.2	Sand Costs.....	538
12.7.3	Tooling Costs .....	539

12.7.4	Processing Costs .....	542
12.8	Design Rules for Sand Castings.....	545
12.8.1	Avoid Sharp Angles and Multiple-Section Joints .....	545
12.8.2	Design Sections of Uniform Thickness .....	546
12.8.3	Proportion Inner Wall Thickness .....	547
12.8.4	Consider Metal Shrinkage in the Design .....	547
12.8.5	Use a Simple Parting Line .....	547
12.8.6	Define Appropriate Machining Allowances.....	548
12.8.7	Use Economical Tolerances .....	548
12.9	Example Calculations.....	549
	References .....	556
<b>13.</b>	<b>Design for Investment Casting.....</b>	<b>559</b>
13.1	Introduction .....	559
13.2	Process Overview.....	559
13.3	Pattern Materials.....	561
13.4	Pattern Injection Machines .....	561
13.5	Pattern Molds.....	563
13.6	Pattern and Cluster Assembly.....	563
13.7	Ceramic Shell Mold.....	563
13.8	Ceramic Cores.....	564
13.9	Pattern Meltout .....	565
13.10	Pattern Burnout and Mold Firing .....	565
13.11	Knockout and Cleaning .....	565
13.12	Cutoff and Finishing.....	566
13.13	Pattern and Core Material Cost.....	566
13.14	Wax Pattern Injection Cost .....	568
13.15	Fill Time.....	570
13.16	Cooling Time .....	570
13.17	Ejection and Reset Time .....	571
13.18	Process Cost per Pattern or Core .....	573
13.19	Estimating Core Injection Cost .....	574
13.20	Pattern and Core Mold Cost .....	575
13.21	Core Mold Cost.....	579
13.22	Pattern and Cluster Assembly Cost.....	579
13.23	Number of Parts per Cluster .....	581
13.24	Pattern Piece Cost.....	582
13.25	Cleaning and Etching.....	583
13.26	Shell Mold Material Cost.....	583
13.27	Investing the Pattern Cluster.....	584
13.28	Pattern Meltout.....	585
13.29	Burnout, Sinter, and Preheat.....	585
13.30	Total Shell Mold Cost.....	585
13.31	Cost for Melting Metal .....	586
13.32	Raw Base Metal Cost .....	590
13.33	Ready-to-Pour Liquid Metal Cost.....	590
13.34	Pouring Cost .....	590
13.35	Final Material Cost.....	591

13.36 Breakout.....	592
13.37 Cleaning .....	593
13.38 Cutoff .....	593
13.39 Design Guidelines.....	596
References.....	597
<b>14. Design for Hot Forging.....</b>	<b>599</b>
14.1 Introduction .....	599
14.2 Characteristics of the Forging Process.....	599
14.2.1 Types of Forging Processes .....	599
14.3 Role of Flash in Forging .....	600
14.3.1 Determination of the Flash Land Geometry .....	601
14.3.2 Amount of Flash .....	603
14.3.3 Webs in Forgings .....	605
14.4 Forging Allowances.....	605
14.5 Preforming during Forging.....	606
14.5.1 Die Layout.....	611
14.6 Flash Removal .....	613
14.7 Classification of Forgings.....	614
14.7.1 Forging Complexity.....	616
14.7.1.1 Shape Complexity Factor .....	616
14.7.1.2 Number of Surface Patches in the Part .....	617
14.8 Forging Equipment.....	617
14.8.1 Gravity Drop Hammers.....	617
14.8.2 Double Acting or Power Hammers.....	618
14.8.3 Vertical Counterblow Hammers.....	618
14.8.4 Horizontal Counterblow Hammers .....	619
14.8.5 Mechanical Presses.....	619
14.8.6 Screw Presses .....	620
14.8.7 Hydraulic Presses .....	620
14.8.8 Choice of Forging Machine Type.....	620
14.8.9 Comparisons of Forging Equipment.....	621
14.9 Classification of Materials.....	621
14.10 Forging Costs.....	624
14.10.1 Material Costs.....	626
14.10.2 Equipment Operating Costs.....	627
14.10.3 Examples of Equipment Selection .....	629
14.10.4 Forging Processing Costs.....	630
14.10.5 Forging Machine Setup Costs.....	632
14.11 Forging Die Costs.....	633
14.11.1 Initial Die Costs.....	633
14.11.2 Estimation of Costs for Multi-Impression Forging Dies .....	634
14.11.2.1 Die Material Costs.....	634
14.11.2.2 Multi-Impression Die Manufacturing Costs.....	636
14.12 Die Life and Tool Replacement Costs.....	638
14.13 Costs of Flash Removal .....	640
14.13.1 Flash Removal Processing Costs .....	640
14.13.2 Tooling Costs for Flash Removal .....	641

14.14 Other Forging Costs .....	642
14.14.1 Billet Preparation .....	642
14.14.2 Billet Heating Costs .....	643
References .....	646
<b>Index</b> .....	<b>649</b>