

# Industrial Applications of X-Ray Diffraction

edited by

**Frank H. Chung**

*Sherwin-Williams Company  
Chicago, Illinois*

**Deane K. Smith**

*The Pennsylvania State University  
University Park, Pennsylvania*



MARCEL DEKKER, INC.

NEW YORK • BASEL

# Contents

<i>Preface</i>	<i>iii</i>
<i>Contributors</i>	<i>xiii</i>

## I. Introduction

1. The Principles of Diffraction Analysis	3
<i>Frank H. Chung and Deane K. Smith</i>	
1. History of Powder Diffraction Analysis	3
2. Fundamentals of X-Ray Diffraction	5
3. Single-Crystal Versus Powder Diffraction	6
4. Types of Radiation Used for Diffraction Analysis	9
5. Safety and Regulations in the Diffraction Laboratory	10
References	10
2. The Practice of Diffraction Analysis	13
<i>Frank H. Chung and Deane K. Smith</i>	
1. Sources of Radiation	13
2. Diffraction Instrumentation	15
3. Crystallographic Databases	16
4. Extraction of Information from Diffraction Patterns	20
5. Analytical Methods	21
6. The Computer in Diffraction Analysis	30
7. Advantages of Diffraction Analysis	31
References	32
3. Progress and Potential of X-Ray Diffraction	37
<i>Frank H. Chung and Deane K. Smith</i>	
1. Introduction	37
2. Evolution	37
3. Progress	39
4. Potentials	48
5. Conclusions	51
References	52

## II. Industrial Applications

### High-Tech

4. Semiconductors: Integrated Circuit Manufacture	55
<i>C. C. Goldsmith, I. C. Noyàn, Patrick De Haven, and T. L. Nunes</i>	

1. Introduction	55
2. Applications	57
References	86
5. Superconductors: Structures and Applications	89
<i>Winnie Wong-Ng</i>	
1. Introduction	89
2. Applications of X-Ray Diffraction	92
3. Summary	122
References	122
6. Aerospace: The Aircraft Gas Turbine Industry	129
<i>H. Jones</i>	
1. Background and Definitions	129
2. Applications to Superalloys	131
3. Applications to Superalloys: Inspection of Cast Single-Crystal Components by the Laue Method	137
4. Automation of the Laue Process—SCORPIO	138
5. Research Activity for Directional Solidified Castings	145
6. Solid-State Processing of Superalloy Single Crystals	146
7. Phase Analysis of Superalloys	149
8. Applications to Alloy Design: Gamma-Gamma Prime Misfit	164
9. Rolling Elements	167
10. Residual Stress Analysis	169
11. Analysis of Phases in Thermal Barrier Coatings	171
12. Hardware and Software Recommendations	174
References	175
7. Selected Applications of X-Ray Diffraction in the Automotive Industry	179
<i>C. K. Lowe-Ma and M. J. Vinarcik</i>	
1. General Considerations	179
2. Qualitative Analysis by Phase Identification	181
3. Quantitative Phase Analysis	187
4. Residual Stress/Retained Austenite	189
References	191
8. Petroleum Exploration and Production	193
<i>Sampath S. Iyengar</i>	
1. Introduction	193
2. Petroleum Exploration	193
3. Petroleum Production and Formation Damage	202
4. Identification of Scales, Drilling Mud, and Reaction Products	204
References	204
9. Petroleum and Petrochemicals	207
<i>James A. Kaduk</i>	
1. Introduction	207
2. Principles and Instrumentation	207
3. Technical Procedures	208
4. Illustrative Examples	208
5. Conclusions	252
References	253
10. Petroleum Catalysts	257
<i>Ronald C. Medrud</i>	
1. Introduction	257

2. Principles and Instrumentation	261
3. Technical Procedures	264
4. Illustrative Examples	266
5. Conclusions	278
References	279
11. Petrochemicals: Vitality of Catalysts Research	287
<i>Ray Teller</i>	
1. The Importance of Catalysis in the Petrochemical Industry	287
2. Types of Diffraction and Their Uses	288
3. Examples of Specific Applications	292
4. The Future of Diffraction in the Petrochemical Industry	300
References	301

## Metals

12. Hydrometallurgy	303
<i>T. Havlik and M. Skrobjan</i>	
1. What Is Hydrometallurgy?	303
2. Problems and Weak Points in Hydrometallurgy	303
3. Some Examples of Application	305
4. Conclusion	313
Suggested Reading	313
13. X-Ray Fractography	317
<i>Y. Hirose and T. Sasaki</i>	
1. Introduction	317
2. Residual Stress Management	330
3. Gradient (Depth Profile) of Residual Stress	353
4. Use of Image Plate for X-Ray Stress Measurement	364
References	370

## Minerals and Ceramics

14. Mining: Exploration and Process Control	373
<i>Johan de Villiers</i>	
1. Introduction	373
2. Applications to Exploration	373
3. Applications to Mineral Dressing	374
4. Applications to Hydrometallurgical Processes	375
5. XRD in Pyrometallurgical Processes	376
6. XRD in On-line Process Control	377
7. Materials Characterization	379
8. Coal and Carbonaceous Materials	381
9. Applications to Health and Environmental Studies	381
10. Summary	382
References	382
15. Mining: Mineral Ores and Products	385
<i>Frank R. Feret</i>	
1. Introduction	385
2. Role of Methods Other than XRD in Mineral Analysis	386

3. XRD Methods	388
4. Iron Minerals and Their Identification by XRD	394
5. Selected Applications of the XRD Analysis in the Mining Industry	397
6. Discussion	400
References	401
16. Cement: Quantitative Phase Analysis of Portland Cement Clinker	415
<i>I. C. Madsen and N. V. Y. Scarlett</i>	
1. Introduction	415
2. Method of Production	416
3. Phases in Clinker and Portland Cement	416
4. Non-X-Ray Methods of Phase Analysis	428
5. Methods of XRD Analysis	428
6. Accuracy of X-Ray Methods	435
7. Conclusions	437
References	437
17. Silica	441
<i>N. J. Elton and Deane K. Smith</i>	
1. Introduction	441
2. Principles of Silica Analysis	445
3. Errors and Uncertainties in Quantitative XRD	453
4. Technical Procedures and Issues	459
5. Conclusions	465
References	466
18. Glass–Ceramics	471
<i>Hans J. Holland</i>	
1. Introduction	471
2. Instrumentation, Techniques, and Sample Preparation	474
3. Application of Techniques	476
4. Related Techniques	488
5. Summary	491
References	492
<b>Polymers and Composites</b>	
19. Polymer Industry	495
<i>N. Sanjeeva Murthy and Randolph Barton, Jr.</i>	
1. Introduction	495
2. Instrumentation	496
3. Data Analysis and Interpretation	496
4. Significance of XRD Results	507
References	507
20. Paint and Pigment Industry	511
<i>Frank H. Chung</i>	
1. Introduction	511
2. X-Ray Diffraction for Chemical Analysis	513
3. Applications	521
4. Conclusions	523
References	524
21. Pharmaceuticals: Development and Formulation	527
<i>Joel Bernstein and Jan-Olav Henck</i>	

1. Introduction	527
2. Principles, Instrumentation, and Technical Procedures	528
3. Applications	528
4. Summary and Prospects	536
References	537
22. Pharmaceuticals: Design and Development of Drug Delivery Systems	539
<i>Jamshed Anwar</i>	
1. Introduction	539
2. Significance of the Solid State in Pharmaceuticals and the Role of PXRD	540
3. Special Challenges	541
4. Characterization	542
5. Quantitative Phase Analysis	544
6. Crystallite Size and Quality	547
7. Ab Initio Structure Solution and Refinement	547
8. Real-Time Dynamic PXRD	548
9. Concluding Remarks	551
References	552
<b>Chemicals</b>	
23. Energy: By-Products of Coal Combustion in Power Plants	555
<i>Gregory J. McCarthy</i>	
1. Introduction	555
2. XRD Technical Procedures	557
3. Mineralogy of Coal Combustion By-Products	558
4. Conclusions	570
References	570
24. Lighting: Design and Development of Luminescent Materials	573
<i>T. Jüstel, H. Nikol, and C. Ronda</i>	
1. Introduction	573
2. Principles and Instrumentation	573
3. Technical Procedures	574
4. Illustrative Examples of the Use of XRD in Research Dealing with Luminescent Materials	574
5. Conclusions	586
References	586
25. Photography: Image Capture and Image Storage Materials	589
<i>T. N. Blanton</i>	
1. Introduction	589
2. Instrumentation	590
3. Procedures	592
4. Examples of Image Capture and Image Storage Materials Analysis Using XRD	597
5. The Role of XRD in Future Directions of the Photographic Industry	606
References	607
26. Detergents and Cleaners: Phase Analysis of Sodium Phosphates	609
<i>T. F. Quail and J. K. M. Chun</i>	
1. Introduction	609
2. Principles and Instrumentation	611
3. Technical Procedures	612
4. Illustrative Examples	613

5. Conclusions	619
References	619
27. Museum: Art and Archaeology	621
<i>Michael Mantler, Manfred Schreiner, and François Schweizer</i>	
1. Introduction	621
2. Significance of Analysis in Art and Archaeology	622
3. Analytical Techniques	623
4. Analysis of Materials in Artistic and Historic Objects	635
5. Identification of Technologies	642
6. Aging and Destruction of Artifacts	647
7. Is It a Fake?	656
References	656
28. Forensic Science: Every Contact Leaves a Trace	659
<i>David F. Rendle</i>	
1. Forensic Science	659
2. Instrumentation	664
3. Technical Procedures	665
4. Illustrative Examples of Forensic Casework	670
5. Summary	671
References	673
29. U.S. Customs Laboratories	677
<i>Martin H. Liberman</i>	
1. Introduction	677
2. Diffraction Instrumentation Used By Customs Laboratories	679
3. Technical Procedures	680
4. Illustrative Examples	681
5. Conclusions	684
6. References	685
30. Commercial Service Laboratory	687
<i>W. N. Schreiner</i>	
1. Commercial Service Laboratories	687
2. Laboratory Operation	695

### III. Specialty Techniques

#### Radiation

31. Synchrotron Usage by Industry	705
<i>Richard Harlow</i>	
1. Uniqueness of Synchrotron X-Radiation for Powder Diffraction	705
2. General Considerations for a Synchrotron Powder Experiment	715
3. Examples	718
References	728
32. Electron Microscopy in Industry	733
<i>Z. G. Li</i>	
1. Introduction	733
2. Electron Diffraction of Micrometer- and Nanometer-Size Crystals	736
3. Conclusions	746
References	747

**Microstructures and Instrumentation**

33. Line Profiles and Sample Microstructure	751
<i>J. Ian Langford</i>	
1. Introduction	751
2. Characteristics of Diffraction Line Profiles	752
3. Sample Microstructure: Theoretical Considerations	759
4. Practical Examples	767
5. Summary of Procedure for Line-Profile Analysis	772
References	773
34. Thin Films and Multilayers	777
<i>Paul F. Fewster</i>	
1. Introduction	777
2. Principles and Instrumentation	778
3. Technical Procedures	782
4. Illustrative Examples	783
5. Conclusion	789
References	790
35. Residual Stress and Stress Gradients	793
<i>Ivo Kraus and Nikolaj Ganev</i>	
1. Load and Residual Stresses	793
2. Macroscopic State of Stress of Crystal Lattice	797
3. Stress Measurement by Monochromatic X-Rays	801
4. Illustrative Examples of Industrial Applications	807
References	810
36. Residual Stress Development and Texture Formation During Rolling Contact Loading	813
<i>Aat P. Voskamp and Eric J. Mittemeijer</i>	
1. Introduction: Rolling Contact Fatigue	813
2. Residual Stress Analysis	819
3. Texture Analysis	833
4. General Discussion	841
5. Conclusions	845
References	846
37. Warren–Averbach Applications	847
<i>T. Ungár</i>	
1. Introduction	847
2. Principles	849
3. The Dislocation Model of the Root-Mean-Squared Strains	854
4. Illustrative Examples	858
5. The Average Values of Dislocation Contrast Factors	863
6. Summary	864
References	865
38. Microbeam Crystallographic and Elemental Analysis	869
<i>R. P. Goehner, M. O. Eatough, J. R. Michael, and R. G. Tissot</i>	
1. Introduction to Microbeam Analysis	869
2. Microbeam X-Ray Diffraction	870
3. Diffraction in the Scanning Electron Microscope	876
4. Microbeam X-Ray Fluorescence	882

5. Comparison of Techniques	886
References	888
39. High-Temperature and Nonambient X-Ray Diffraction	891
<i>Mark Rodriguez</i>	
1. Introduction	891
2. Experimental	895
3. Examples	898
References	901

## Diffraction Patterns

40. NIST Standard Reference Materials for Characterization of Instrument Performance	903
<i>James P. Cline</i>	
1. Introduction	903
2. Parameters Defining Instrument Performance and NIST Reference Materials	903
3. Measurements and Analytical Procedures Adopted with NIST Standards	907
4. Conclusions	916
References	916
41. Grain Orientation and Texture	919
<i>Hans J. Bunge</i>	
1. Introduction	919
2. Definition of the Texture	919
3. Texture Determination	923
4. Texture in Materials Science and Technology	934
5. Generalized Textural Quantities	947
6. Particular Examples of Textures in Materials Technology	950
7. Other Applications of Texture Analysis	968
References	972
42. Structure Analysis from Powder Data	975
<i>D. Louër</i>	
1. Introduction	975
2. Origin of the Powder Diffraction Pattern	976
3. Data Collection	978
4. Total Pattern Modeling	980
5. Powder Pattern Indexing	982
6. Structure Analysis from Powder Data	985
7. Applications	987
References	990