

STEELS

Microstructure and Properties

Fourth edition

Sir Harshad Bhadeshia

Tata Steel Professor of Metallurgy
University of Cambridge

Sir Robert Honeycombe[†]

Emeritus Goldsmiths' Professor of Metallurgy
University of Cambridge



ELSEVIER

AMSTERDAM • BOSTON • HEIDELBERG • LONDON
NEW YORK • OXFORD • PARIS • SAN DIEGO
SAN FRANCISCO • SINGAPORE • SYDNEY • TOKYO

Butterworth-Heinemann is an imprint of Elsevier



CONTENTS

<i>Preface to the First Edition</i>	<i>xi</i>
<i>Preface to the Second Edition</i>	<i>xiii</i>
<i>Preface to the Third Edition</i>	<i>xv</i>
<i>Preface to the Fourth Edition</i>	<i>xvii</i>
<i>Acknowledgments</i>	<i>xix</i>
<i>Acronyms</i>	<i>xxi</i>
<i>Nomenclature</i>	<i>xxiii</i>
1. Iron and Its Interstitial Solutions	1
1.1. Introduction	1
1.2. Allotropes of pure iron	3
1.3. Austenite to ferrite transformation	5
1.4. Carbon, nitrogen and hydrogen in solution	11
1.5. Summary	20
References	20
Backnotes	22
2. Strengthening of Iron and Its Alloys	23
2.1. Introduction	23
2.2. Work hardening	25
2.3. Interstitial solid solution strengthening	28
2.4. Substitutional solution strengthening	37
2.5. Grain size	38
2.6. Dispersion strengthening	43
2.7. Overall strength	46
2.8. Some practical aspects	47
2.9. Limits to strength	49
2.10. Summary	54
References	54
Backnotes	57
3. Iron-Carbon Equilibrium and Plain Carbon Steels	59
3.1. Iron-carbon equilibrium phase diagram	59
3.2. Austenite-ferrite transformation	63
3.3. Austenite-cementite transformation	67
3.4. Kinetics of the $\gamma \rightarrow \alpha$ transformation	68
3.5. Widmanstätten ferrite	73
3.6. Austenite-pearlite reaction	78
3.7. Ferrite-pearlite steels	93

3.8. Summary	96
References	97
Backnotes	99
4. Solutes that Substitute for Iron	101
4.1. General principles	101
4.2. Alloying elements: γ and α phase fields	102
4.3. Distribution of alloying elements in steels	107
4.4. Effect of alloying elements on the kinetics of the γ/α transformation	111
4.5. Structural changes resulting from alloying additions	120
4.6. Transformation diagrams for alloy steels	129
4.7. Light steels	130
4.8. Summary	131
References	132
Backnotes	134
5. Formation of Martensite	135
5.1. Introduction	135
5.2. General characteristics	135
5.3. Crystal structure of martensite	142
5.4. Crystallography of martensitic transformations	144
5.5. Morphology of ferrous martensites	148
5.6. Kinetics of martensitic transformation	152
5.7. Strength of martensite	167
5.8. Shape memory effect	172
5.9. Summary	173
References	173
Backnotes	176
6. Bainite	179
6.1. Introduction	179
6.2. Upper bainite ($\approx 550 - 400^\circ\text{C}$)	180
6.3. Lower bainite ($\approx 400 - 250^\circ\text{C}$)	183
6.4. The shape deformation	185
6.5. Carbon in bainite	187
6.6. Kinetics	189
6.7. Transition from upper to lower bainite	192
6.8. Granular bainite	194
6.9. Tempering of bainite	195
6.10. Role of alloying elements	197
6.11. Use of bainitic steels	198
6.12. Summary	201

References	201
Backnotes	202
7. Acicular Ferrite	203
7.1. Introduction	203
7.2. Microstructure	204
7.3. Mechanism of transformation	206
7.4. Inclusions as heterogeneous nucleation sites	210
7.5. Nucleation of acicular ferrite	212
7.6. Summary	214
References	215
Backnotes	216
8. Heat Treatment of Steels: Hardenability	217
8.1. Introduction	217
8.2. Use of TTT and continuous cooling diagrams	218
8.3. Hardenability testing	221
8.4. Effect of grain size and chemical composition on hardenability	226
8.5. Hardenability and heat treatment	226
8.6. Quenching stresses and quench cracks	228
8.7. Cryogenic treatment	233
8.8. Summary	234
References	235
Backnotes	236
9. Tempering of Martensite	237
9.1. Introduction	237
9.2. Tempering involving cementite and transition carbides	238
9.3. Mechanical properties of tempered martensite	246
9.4. Steels with strong carbide-forming elements	248
9.5. Maraging steels	266
9.6. Summary	267
References	268
Backnotes	270
10. Thermomechanical Treatment of Steels	271
10.1. Introduction	271
10.2. Controlled rolling of low-alloy steels	273
10.3. Dual-phase steels	287
10.4. TRIP-assisted steels	288
10.5. TWIP steels	294
10.6. Industrial steels subjected to thermomechanical treatments	296
10.7. Ausforming	297

10.8. Summary	298
References	299
Backnotes	301
11. The Embrittlement and Fracture of Steels	303
11.1. Introduction	303
11.2. Cleavage fracture in iron and steel	304
11.3. Factors influencing the onset of cleavage fracture	308
11.4. Criteria for the ductile-brittle transition	310
11.5. Practical aspects of brittle fracture	313
11.6. Hydrogen embrittlement	316
11.7. Intergranular embrittlement	321
11.8. Ductile or fibrous fracture	327
11.9. Summary	337
References	337
Backnotes	340
12. Stainless Steel	343
12.1. Introduction	343
12.2. The iron-chromium-nickel system	345
12.3. Chromium-rich carbide in Cr-Ni austenitic steels	349
12.4. Precipitation of niobium and titanium carbides	353
12.5. Nitrides in austenitic steels	356
12.6. Intermetallic precipitation in austenite	356
12.7. Austenitic steels in practical applications	358
12.8. Oxidation resistant stainless steel	360
12.9. Duplex and ferritic stainless steels	362
12.10. Mechanically alloyed stainless steels	366
12.11. Transformation of metastable austenite	369
12.12. Summary	374
References	374
Backnotes	376
13. Weld Microstructures	377
13.1. Introduction	377
13.2. Fusion zone	377
13.3. Heat-affected zone	388
13.4. Friction stir welding of steels	395
13.5. Summary	398
References	399
Backnotes	400

14. Nanostructured Steels	401
14.1. Introduction	401
14.2. Why the yearning for exceedingly fine grains?	402
14.3. Production of nanostructured steel	404
14.4. Detrimental nanostructures in steels	415
14.5. Summary	416
References	417
Backnotes	419
15. Modelling of Structure and Properties	421
15.1. Introduction	421
15.2. Example 1: alloy design	425
15.3. Example 2: mechanical properties of mixed microstructures	433
15.4. Methods	439
15.5. Kinetics	445
15.6. Finite element method	448
15.7. Neural networks	449
15.8. Summary	452
References	452
Backnotes	455
<i>Subject index</i>	457