

Jürgen Wittmann

Integrated High- V_{in} Multi-MHz Converters



Springer

Contents

1	Introduction	1
1.1	Scope of This Book	3
1.2	Outline of This Book	4
1.2.1	Motivation for High- V_{in} Converters and Fundamentals	4
1.2.2	Fast-Switching High- V_{in} Buck Converters	4
1.2.3	Design of Fast-Switching Circuit Blocks	5
1.2.4	Efficiency and Loss Modeling of High- V_{in} Multi-MHz Converters	5
1.2.5	Dead Time Control	6
1.2.6	Resonant Converters	6
1.2.7	Conclusion and Outlook	7
	References	7
2	Motivation for High-V_{in} Converters and Fundamentals	9
2.1	Applications for High- V_{in} DC-DC Converters	9
2.1.1	Automotive and e-Mobility	9
2.1.2	Servers	12
2.1.3	Automation	15
2.1.4	Mobile Devices	16
2.2	Power Conversion to Low-Voltage Components	16
2.2.1	DC-DC Conversion Fundamentals	16
2.2.2	Types of DC-DC Converters	18
2.3	Buck Converter Fundamentals	26
2.3.1	Buck Converter Parameters	26
2.3.2	Scaling of the Output Filter	28
2.3.3	Scaling of Real Inductors	30
2.3.4	Scaling of Real Capacitors	33
2.3.5	Losses in a Buck Converter	34
2.3.6	Design Challenges for High- V_{in}	39
2.4	State-of-the-Art Converters	41
	Appendix	42
	References	43

3	Fast-Switching High-V_{in} Buck Converters	47
3.1	Buck Converter Architectures	47
3.2	Power Switch Technologies	51
3.3	Converter Implementation Aspects	53
3.4	Substrate Coupling	56
3.4.1	Comparison of Isolation Structures by Simulation	58
3.4.2	Verification of Isolation Structures by Measurements	62
	References	64
4	Design of Fast-Switching Circuit Blocks	67
4.1	Output Voltage Regulation	67
4.2	Sawtooth and PWM Generator	69
4.2.1	Requirements for Sawtooth and PWM Generator	69
4.2.2	Limitations of Conventional Sawtooth Generators	70
4.3	Level Shifters	75
4.3.1	Conventional Level Shifter Concepts	76
4.3.2	Level Shifter for PMOS High-Side Switches	77
4.3.3	Level Shifter for NMOS High-Side Switches	78
4.4	Gate Driver	81
4.5	Experimental Results of Fast-Switching Circuit Blocks	83
	References	86
5	Efficiency and Loss Modeling of High-V_{in} Multi-MHz Converters	89
5.1	Conventional Efficiency Modeling	90
5.2	Priorities of Loss Modeling for High- V_{in} Fast-Switching Converters	90
5.3	Efficiency Model for an Asynchronous Buck Converter	92
5.3.1	Diode Conduction Losses	93
5.3.2	Switching Behavior	93
5.3.3	Implementation as Four-Phase Model	96
5.3.4	Root Cause and Loss Location Analysis	98
5.3.5	Contribution and Modeling of Non-linear Capacitances	99
5.4	Loss Contributions in a Synchronous Buck Converter	104
5.4.1	Contribution of the Low-Side Switch	104
5.4.2	Influence of Dead Time on Switching Behavior	105
5.4.3	Dead Time Related Losses	106
5.4.4	Dead Time Related Losses at Light Load	110
5.5	Loss Optimization and Limitations	113
5.6	Architecture Comparison	114
5.7	Design Indicator: Efficiency Scaling	117
	Appendix	120
	References	122
6	Dead Time Control	125
6.1	State-of-the-Art Dead Time Controls	125
6.2	Predictive Mixed-Signal Dead Time Control	126
6.2.1	Dead Time Control Concept	126

6.2.2	Sample and Hold Circuit	128
6.2.3	Differential Delay Lines	130
6.2.4	Experimental Results	132
6.3	Enhanced Dead Time Control for Light Load	136
6.3.1	Turn-High Dead Time Control Concept	137
6.3.2	Experimental Results	138
	References	139
7	Resonant Converters	141
7.1	Quasi-Resonant Converter	141
7.2	Parallel-Resonant Converter (PRC)	144
7.2.1	Switching Concept and Operating Modes	145
7.2.2	Converter Implementation	147
7.2.3	Experimental Results	149
	References	157
8	Conclusion and Outlook.....	161
8.1	Conclusion	161
8.2	Comparison to State-of-the-Art	164
8.3	Outlook	165
	References	167
	Index.....	169