

Theory of Transformations in Steels

Harshad K. D. H. Bhadeshia



CRC Press

Taylor & Francis Group

Boca Raton London New York

CRC Press is an imprint of the
Taylor & Francis Group, an **informa** business

Contents

Preface.....	xv
Author	xix
Acronyms etc.	xxi
Nomenclature.....	xxiii
Chapter 1 Crystal structures and mechanisms	1
1.1 Allotropes of iron.....	1
1.2 The illusory omega phase	5
1.3 Amorphous iron	6
1.4 Mechanisms of transformation	6
1.5 Crystallographic similarities.....	8
1.6 Iron-carbon phase diagram	9
1.7 Classification scheme.....	11
1.7.1 Thermodynamic Classification	13
Chapter 2 Thermodynamics	17
2.1 Introduction.....	17
2.2 Definitions.....	17
2.2.1 Internal energy and enthalpy	17
2.2.2 Entropy, free energy	18
2.2.3 Configurational entropy	18
2.2.4 Relationship between Clausius and Boltzmann entropies	19
2.3 Maxwell relations	20
2.4 Thermodynamic functions of iron	20
2.4.1 Relation between C_p and C_v	22
2.4.2 Debye Temperatures	22
2.5 Electronic heat capacity	23
2.6 Magnetic specific heat of iron.....	24
2.6.1 Diamagnetism	25
2.6.2 Paramagnetism	25
2.6.3 Ferromagnetism, antiferromagnetism and ferrimagnetism.....	26
2.6.4 Heat capacity due to magnetisation	27
2.6.5 Magnetic heat capacity of ferrite	28
2.6.6 Magnetic heat capacity of austenite.....	30
2.6.7 Invar effect and associated phenomena.....	35
2.6.8 Magnetic heat capacity of ϵ -Iron and superconductivity	38
2.6.9 Trigonal and tetragonal iron.....	39
2.7 Heat capacity of liquid iron	44
2.8 Free energy functions of iron.....	44
2.8.1 Liquid iron	45

2.9	Effect of pressure	47
2.9.1	Liquid iron	47
2.9.2	Ferrite and austenite	48
2.9.3	Hexagonal close-packed iron	49
2.10	Mechanical mixtures and solutions	49
2.10.1	Alloying by deformation	49
2.11	Chemical potential	51
2.12	Equilibrium between solutions	52
2.13	Activity	53
2.14	Ideal solution	54
2.15	Regular solutions	55
2.16	Quasichemical solution	57
2.17	quasichemical model for carbon in austenite	61
2.17.1	Dilute solution, $\omega_\gamma \rightarrow 0$ limit	66
2.17.2	Infinite repulsion limit	66
2.17.3	Zeroth-order quasichemical model	67
2.17.4	Reference state for carbon	67
2.17.5	Carbon-carbon interaction energy in austenite	67
2.17.6	Carbon-carbon interaction energy in ferrite	70
2.18	Zener ordering	71
2.19	Computer calculation of phase diagrams	72
2.19.1	Stoichiometric phases: regular solution model	73
2.19.2	Interstitial solution	74
2.19.3	Generalised regular solution model	77
2.19.4	Magnetic effects	78
2.19.5	Magnetisation	84
2.20	Order parameter	84
2.20.1	Short-range order	86
2.21	Superlattices	87
2.21.1	Ordered crystals	87
2.22	Thermodynamics of irreversible processes	88
2.22.1	Reversibility	89
2.22.2	Linear laws	90
2.22.3	Multiple irreversible processes	91
2.22.4	Onsager reciprocal relations	92
Chapter 3	Diffusion	103
3.1	Introduction	103
3.2	Fick's law and diffusion coefficients	103
3.2.1	Reaction rate expression	107
3.3	Diffusion of carbon in ferrite	107
3.3.1	Interstitial sites in ferrite	107
3.3.2	Dual-site occupancy	110
3.4	Diffusion of carbon in martensite	112
3.5	Interactions between carbon atoms	114
3.5.1	Repulsion between carbon atoms	114
3.5.2	Clustering of interstitial atoms	115
3.5.3	Association of carbon with defects	117
3.6	Diffusion of carbon in austenite	119
3.6.1	Dependence of diffusivity on composition	119

3.6.2	Dependence of diffusivity on C-C interactions.....	121
3.6.3	Dilatation effects.....	123
3.6.4	Ågren's method.....	125
3.7	Diffusion of nitrogen in ferrite.....	126
3.8	Diffusion of nitrogen in austenite.....	127
3.9	Diffusion of C and N in cementite and Hägg carbide.....	127
3.10	Migration of point defects.....	129
3.10.1	Iron interstitials.....	129
3.10.2	Iron defects in austenite.....	130
3.10.3	Vacancies.....	131
3.11	Migration of hydrogen and deuterium.....	132
3.11.1	Diffusion in ferrite.....	132
3.11.2	Diffusion of hydrogen in austenite.....	133
3.11.3	Hydrogen-vacancy interactions.....	134
3.12	Self-diffusion in iron.....	134
3.12.1	The isotope effect.....	138
3.13	Magnetism and interstitial diffusion in ferrite.....	139
3.14	Substitutional solutes.....	140
3.15	Grain boundary diffusion.....	142
3.16	Phenomenological treatment of binary diffusion.....	143
3.17	Diffusion in multicomponent systems.....	144
3.17.1	Diffusion in ternary Fe-X-C alloys.....	145
3.18	Diffusion in liquid iron.....	148
3.19	Stress-induced migration.....	149
3.20	Electromigration.....	150
3.21	Thermomigration.....	153
3.22	Electropulsing.....	154

Chapter 4	Ferrite by reconstructive transformation.....	165
4.1	Introduction.....	165
4.2	Interfaces.....	167
4.2.1	Coherency.....	167
4.2.2	Glissile semi-coherent interfaces.....	168
4.2.3	Sessile semi-coherent interfaces.....	169
4.2.4	Incoherent interfaces.....	170
4.3	Crystallography.....	170
4.3.1	Orientation relationships.....	170
4.3.2	The γ/α interface.....	174
4.4	Nucleation of allotriomorphic and idiomorphic ferrite.....	174
4.4.1	Heterogeneous nucleation from vapour.....	178
4.4.2	Heterogeneous nucleation on inclusions.....	180
4.5	Interface motion: rate-controlling processes.....	184
4.6	Diffusion-controlled growth.....	187
4.6.1	Growth in Fe-C Alloys.....	187
4.6.2	Lengthening of ferrite allotriomorphs.....	190
4.6.3	Soft impingement.....	191
4.6.4	Phase fields.....	192
4.6.5	Ferrite growth in Fe-X-C alloys: local equilibrium.....	194
4.6.6	Interface-composition contours.....	200
4.6.7	Interface-velocity (IV) contours.....	201

4.6.8	Tie-line shifting due to soft impingement.....	202
4.6.9	Invalidity of the NP-LE concept.....	204
4.7	Breakdown of local equilibrium.....	207
4.7.1	Paraequilibrium.....	207
4.7.2	Solute and solvent trapping.....	210
4.8	Interface-controlled growth.....	215
4.8.1	Pure iron.....	215
4.8.2	Iron alloys.....	217
4.9	Growth with mixed control.....	217
4.10	Step mechanism of interfacial motion.....	220
4.10.1	Boundary topology, ledge nucleation.....	220
4.10.2	Motion of isolated ledge.....	223
4.10.3	Multiledge interactions.....	227
4.10.4	Ledge motion in finite medium.....	228
4.10.5	Relative kinetics of stepped and continuous growth.....	229
4.11	Solute drag: grain boundaries.....	231
4.11.1	Solute drag and diffusion coefficients.....	234
4.11.2	Interaction free energy.....	234
4.12	Solute drag: interphase boundaries.....	235
4.12.1	Segregation to α/γ interfaces.....	235
4.13	Massive ferrite.....	236
4.14	Interphase precipitation.....	239
4.14.1	Interphase precipitation: theory.....	240
Chapter 5	Martensite.....	255
5.1	Diffusionless transformations.....	255
5.2	Other characteristics of martensite.....	257
5.2.1	Habit plane.....	260
5.2.2	Orientation relationships.....	260
5.2.3	Structure of the interface.....	263
5.2.4	Shape deformation.....	268
5.2.5	Microstructure.....	268
5.2.6	Summary.....	270
5.2.7	Crystallographic theory.....	271
5.3	Quantitative theory.....	272
5.3.1	fcc to bcc martensitic transformation.....	272
5.4	ϵ -martensite.....	278
5.4.1	Crystallography: fcc to hcp transformation.....	278
5.4.2	$\alpha \rightarrow \epsilon$ transformation.....	281
5.5	Martensite-start temperature.....	282
5.5.1	Effect of austenite grain size on M_S	285
5.6	Thermodynamics.....	287
5.6.1	Thermoelastic equilibrium.....	289
5.7	Martensite: nucleation mechanism.....	291
5.7.1	fcc to hcp transformation.....	291
5.7.2	Role of thermal activation.....	294
5.7.3	fcc to bcc transformation.....	295
5.7.4	Nucleation at large driving forces.....	297
5.8	Overall transformation kinetics.....	300
5.8.1	Partitioning of austenite.....	301

5.8.2	Athermal transformation.....	304
5.8.3	Isothermal martensite.....	305
5.8.4	Bursts of transformation	308
5.9	Stress AND strain effects.....	310
5.9.1	Transformation texture.....	312
5.9.2	Mechanical stabilisation.....	314
5.10	Tetragonality of martensite.....	316
Chapter 6	Bainite.....	329
6.1	Microstructure.....	329
6.2	More about the mechanism.....	332
6.2.1	Stage 1: vestiges.....	334
6.2.2	Stage 2a: carbon partitioning	335
6.2.3	Stage 2b: precipitation from ferrite.....	336
6.2.4	Stage 3: termination	337
6.3	Kinetics.....	340
Chapter 7	Widmanstätten ferrite	349
7.1	Introduction.....	349
7.2	Crystallography.....	351
7.3	Accommodation of shape deformation.....	354
7.3.1	Interfacial structure	356
7.3.2	Mechanical stabilisation.....	356
7.4	Transformation-start temperature	357
7.5	Mechanism of nucleation.....	359
7.6	Rationalisation of shear transformations	361
7.7	Nucleation rate.....	363
7.8	Capillarity	364
7.9	Growth of Widmanstätten ferrite	365
7.9.1	Interface-controlled growth.....	370
7.9.2	Groups of plates	370
7.10	Plate thickening	372
7.11	Growth from allotriomorphic ferrite.....	374
Chapter 8	Cementite.....	381
8.1	Crystal structure of cementite.....	383
8.1.1	Types of interstitial sites	384
8.2	Carbon content of cementite.....	385
8.3	Magnetic properties	387
8.4	Thermal properties.....	389
8.5	Surface energy	390
8.6	Elastic properties of single crystalline cementite	391
8.7	Elastic properties of polycrystalline cementite.....	393
8.8	Substitutional solutes.....	394
8.8.1	Precipitates inside cementite.....	397
8.9	Thermodynamic properties.....	398
8.9.1	Heat capacity.....	398
8.9.2	Equilibrium between cementite and matrix dislocations.....	399
8.9.3	Graphitisation and synthesis	399

8.10	Cementite precipitation in metallic glass.....	400
8.11	Carbon nanotubes – role of cementite	401
8.12	Displacive mechanism of cementite precipitation	402
8.13	α/θ orientation relations in pearlite	406
8.14	Pitsch γ/θ orientation relationship.....	407
Chapter 9	Other Fe-C carbides.....	419
9.1	Generic considerations.....	419
9.1.1	Observations of χ , η , ε and θ carbides in tempered Fe-C	420
9.2	χ -carbide	422
9.3	η -carbide	425
9.4	ε -carbide	427
9.4.1	Elastic moduli of ε -carbide	433
Chapter 10	Nitrides	445
10.1	γ' -nitride	446
10.2	ε -nitrides	448
10.3	ζ -Fe ₂ N	450
10.4	α'' -Fe ₁₆ N ₂	451
10.5	Z-phase	453
10.6	Nb(CN), CrN, TiN, Cr ₂ N, AlN	454
Chapter 11	Substitutionally alloyed precipitates.....	463
11.1	TiC, NbC.....	463
11.2	Vanadium carbide	467
11.3	M ₂₃ C ₆	469
11.4	M ₆ C	471
11.5	M ₇ C ₃	473
11.6	Mo ₂ C	475
11.7	κ -carbide.....	478
11.8	Laves phase.....	480
11.9	Other intermetallic compounds.....	481
11.9.1	NiAl.....	482
11.9.2	σ -phase	482
11.9.3	μ -phase.....	484
11.9.4	Iron-zinc compounds	485
11.10	Competitive precipitation and dissolution	487
Chapter 12	Pearlite.....	497
12.1	Shape.....	497
12.2	Nucleation.....	500
12.3	Growth	503
12.4	Fe-C-X: growth with local equilibrium	508
12.4.1	Local equilibrium?.....	510
12.5	Forced velocity pearlite	512
12.6	Pearlite not containing cementite.....	512
12.7	Divorced eutectoid transformation	513

Chapter 13	Aspects of kinetic theory	519
13.1	Grain growth	519
13.2	Recrystallisation	521
13.2.1	Phenomenological treatment of recrystallisation.....	524
13.2.2	Thermomechanical processing: limits to grain refinement.....	525
13.3	Overall transformation kinetics	526
13.3.1	Isothermal transformation.....	526
13.4	Simultaneous transformations	528
13.4.1	Basis of microstructural models.....	529
13.4.2	Allotriomorphic ferrite.....	529
13.4.3	Widmanstätten ferrite and pearlite.....	532
13.5	Time-temperature-transformation diagrams	535
13.5.1	Continuous cooling transformation diagrams.....	537
	Author index	544
	Subject index.....	568