

**Berichte aus dem
Institut für Eisenhüttenkunde**



IEHK
RWTH Aachen

Carsten Greisert

**Strain-induced formation of martensite
during forming and springback behaviour
of annealed and hard cold-rolled stainless
steel grades EN 1.4301 and EN 1.4318**

Herausgeber:

Prof. Dr.-Ing. W. Bleck
Prof. Dr.rer.nat. Dr.-Ing.e.h. W. Dahl
Prof. Dr.-Ing. T. El Gammal
Prof. Dr.-Ing. H.W. Gudenau
Prof. Dr.-Ing. D. Senk

Band 5/2004

Shaker Verlag
D 82 (Diss. RWTH Aachen)

Table of Contents

	List of symbols	IV
1	Introduction	1
2	Objectives	3
3	State of the Art	6
3.1	Automotive Lightweight Construction	6
3.2	Stainless Steel for Automotive Components	8
3.3	Materials and Technology	10
3.3.1	Production of Stainless Steel	10
3.3.2	Lattice and Defects in Metals	13
3.3.3	Martensitic Transformation	16
3.4	Mechanical Properties	22
3.4.1	Fundamentals	22
3.4.2	Engineering and True Stress-Strain Curve	23
3.4.3	Mathematical Description of Flow Curves	27
3.4.4	Elastic and Inelastic Strain	29
3.4.5	Influence of Test Parameters on Mechanical Properties	30
3.5	Fundamentals of Stamping	33
3.5.1	Bending	33
3.5.2	Deep Drawing	36
3.5.3	Stretch Forming	37
3.5.4	Complex Forming Operations	38
3.5.5	Influence of Test Parameters on Springback	41
4	Experimental Techniques	45
5	Material	47
5.1	Material Choice	47
5.2	Determination of α' -martensite	49
5.2.1	Metallography	49
5.2.2	X-ray Diffraction	50

5.2.3	Ferritescope	52
5.3	Microstructure	55
5.4	Tribology	58
5.4.1	Roughness	58
5.4.2	Friction	59
5.5	Tensile tests	61
5.5.1	Strain Analysis by Argus and Aramis	61
5.5.2	Material 1.4301-2	62
5.5.3	Material 1.4301-5	68
5.5.4	Temperature Measurements	75
5.5.5	Influence of Material Grade	78
5.5.6	Influence of Test Parameters	81
5.5.7	Comparison to Compression Test	84
5.6	Forming Limit Curve (FLC)	85
6	Forming and Springback	89
6.1	90° Bending	89
6.1.1	Analytical Description	94
6.2	Draw Bending	98
6.2.1	Drawing Force and Springback	99
6.2.2	Analytical Description	103
6.3	Hat Profiles	104
6.3.1	Hat Profiles Stamped without Draw Bead	107
6.3.1.1	Punch Force F_p	108
6.3.1.2	Strain Analysis	110
6.3.1.3	Blankholder Pressure p_{BH}	113
6.3.1.4	Draw Gap u_g	115
6.3.1.5	Die Radius r_d	117
6.3.1.6	Cold Rolling	120
6.3.2	Hat Profiles Stamped with Draw Bead	123
6.3.2.1	Punch Force F_p	123

6.3.2.2	Strain Analysis	125
6.3.2.3	Draw Bead Height h_{db}	128
6.3.2.4	Draw Gap u_g	132
6.3.2.5	Die Radius r_d	133
6.3.2.6	Cold Rolling	135
6.3.3	Statistical Analysis (Capability Study)	138
6.4	Rear Side Member	143
7	Discussion	148
7.1	Determination of α' -martensite	148
7.2	Mechanical Properties	148
7.2.1	Cold Rolling	148
7.2.2	Austenite Stability	150
7.2.3	Stress / Strain State	152
7.3	Forming and Springback	153
7.3.1	90° Bending	153
7.3.2	Draw Bending	153
7.3.3	Hat Profiles	155
7.3.4	Hat Profiles with Draw Beads	157
7.3.5	Transfer to Series Production	158
8	Conclusions	160
9	Summary	162
10	Annex	164
11	Bibliography	168