

GEOLOGICAL SOCIETY SPECIAL PUBLICATION NO. 271

Building Stone Decay: From Diagnosis to Conservation

EDITED BY

R. PŘIKRYL

Charles University, Prague

and

B. J. SMITH

Queen's University, Belfast

2007

Published by
The Geological Society
London

Contents

Preface	vii
SMITH, B. J. & PŘIKRYL, R. Diagnosing decay: the value of medical analogy in understanding the weathering of building stones	1
PŘIKRYL, R. Understanding the Earth scientist's role in the pre-restoration research of monuments: an overview	9
Inventorying built heritage and its raw materials	
CALCATERRA, D., CAPPELLETTI, P., DE' GENNARO, M., DE GENNARO, R., DE SANCTIS, F., FLORA, A. & LANGELLA, A. The rediscovery of an ancient exploitation site of Piperno, a valuable historical stone from the Phlegraean Fields (Italy)	23
FRANGIPANE, A. Natural stone portals of the town of Udine (Italy): their design, construction and materials between the 15th and 20th centuries	33
HOFFMANN, A. & SIEGISMUND, S. The dimension stone potential of Thailand – overview and granite site investigations	43
PEREIRA, D., YENES, M., BLANCO, J. A. & PEINADO, M. Characterization of serpentinites to define their appropriate use as dimension stone	55
ŠIMUNIĆ BURŠIĆ, M., ALJINOVIĆ, D. & CANCELLIERE, S. Kirmenjāk– <i>Pietra d'Istria</i> : a preliminary investigation of its use in Venetian architectural heritage	63
THORNBUSH, M. J. & VILES, H. A. Photo-based decay mapping of replaced stone blocks on the boundary wall of Worcester College, Oxford	69
Patterns and monitoring of decay	
MCCABE, S., SMITH, B. J. & WARKE, P. A. An holistic approach to the assessment of stone decay: Bonamargy Friary, Northern Ireland	77
DIONÍSIO, A. Stone decay induced by fire on historic buildings: the case of the cloister of Lisbon Cathedral (Portugal)	87
FIGUEIREDO, C. A. M., AIRES-BARROS, L., BASTO, M. J., GRAÇA, R. C. & MAURÍCIO, A. The weathering and weatherability of Basilica da Estrela stones, Lisbon, Portugal	99
MARSZALEK, M. The mineralogical and chemical methods in investigations of decay of the Devonian black 'marble' from Dębnik (Southern Poland)	109
Processes of decay	
GROSSI, C. M. & BRIMBLECOMBE, P. Effect of long-term changes in air pollution and climate on the decay and blackening of European stone buildings	117
LEFÈVRE, R.-A., IONESCU, A., AUSSET, P., CHABAS, A., GIRARDET, F. & VINCE, F. Modelling of the calcareous stone sulphation in polluted atmosphere after exposure in the field	131
SIPPEL, J., SIEGISMUND, S., WEISS, T., NITSCH, K.-H. & KORZEN, M. Decay of natural stones caused by fire damage	139
SMITH, B. J., MCALISTER, J. J., BAPTISTA NETO, J. A. & SILVA, M. A. M. Post-depositional modification of atmospheric dust on a granite building in central Rio de Janeiro: implications for surface induration and subsequent stone decay	153
THOMACHOT, C. & MATSUOKA, N. Dilatation of building materials submitted to frost action	167
Salt decay testing	
ANDRIANI, G. F. & WALSH, N. The effects of wetting and drying, and marine salt crystallization on calcarenite rocks used as building material in historic monuments	179
ROTHERT, E., EGGERS, T., CASSAR, J., RUEDRICH, J., FITZNER, B. & SIEGISMUND, S. Stone properties and weathering induced by salt crystallization of Maltese Globigerina Limestone	189

RUEDRICH, J., SEIDEL, M., ROTHERT, E. & SIEGESMUND, S. Length changes of sandstones caused by salt crystallization	199
WARKE, P. A. & SMITH, B. J. Complex weathering effects on durability characteristics of building stone	211
Record of decay in rock properties	
McKINLEY, J. M. & WARKE, P. A. Controls on permeability: implications for stone weathering	225
SCHEFFZÜK, CH., SIEGESMUND, S., NIKOLAYEV, D. I. & HOFFMANN, A. Texture, spatial and orientation dependence of internal strains in marble: a key to understanding the bowing of marble panels?	237
TÖRÖK, Á., FORGÓ, L. Z., VOGT, T., LÖBENS, S., SIEGESMUND, S. & WEISS, T. The influence of lithology and pore-size distribution on the durability of acid volcanic tuffs, Hungary	251
TÖRÖK, Á., SIEGESMUND, S., MÜLLER, C., HÜPERS, A., HOPPERT, M. & WEISS, T. Differences in texture, physical properties and microbiology of weathering crust and host rock: a case study of the porous limestone of Budapest (Hungary)	261
VLASSEN BROECK, J., CNUUDE, V., MASSCHAELE, B., DIERICK, M., VAN HOOREBEKE, L. & JACOBS, P. A comparative and critical study of X-ray CT and neutron CT as non-destructive material evaluation techniques	277
Performance in use and conservation	
CARÒ, F. & DI GIULIO, A. Rock petrophysics v. performance of protective and consolidation treatments: the case of Mt Arzolo Sandstone	287
VAZQUEZ-CALVO, C., ALVAREZ DE BUERGO, M. & FORT, R. Overview of recent knowledge of patinas on stone monuments: the Spanish experience	295
VILES, H. A. & WOOD, C. Green walls?: integrated laboratory and field testing of the effectiveness of soft wall capping in conserving ruins	309
Index	323