

**11TH
INTERNATIONAL
CONGRESS
ON DETERIORATION
AND CONSERVATION
OF STONE**

15-20 SEPTEMBER 2008, TORUN, POLAND

PROCEEDINGS

VOLUME

I

EDITED BY
JADWIGA W. ŁUKASZEWICZ
PIOTR NIEMCEWICZ



WYDAWNICTWO NAUKOWE
UNIWERSYTETU MIKOŁAJA KOPERNIKA

TABLE OF CONTENT VOLUME 1

Introduction (Łukaszewicz J.W.) xxi

Theme 1 – Ethical issues in conservation

Siegl P., *Ethical Problems in the Restoration Praxis in the Czech Republic* 1

Theme 2 – Deterioration of stone, ceramic, plaster

Almeida A., Begonha A., *Stone Deterioration in Monuments of Northern Portugal* 7

Arroyo F., Alcalde M., Villegas R., Robador M. D., *Effects of Conservation Products on the Colour of Stone Materials. Response to Radiation UV* 15

Begonha A., *Granite Deterioration in Two Portuguese Churches and Characterization of the Salt Solutions in the Porous Network by the Presence of Diatoms* 23

Benchiarin S., Fassina V., Molin G., *New Facets on the Deterioration of Nanto Stone* 31

Bugini R., Colombo C., Folli L., *Conglomerates from Lombardy (Northern Italy) Features and Decay Phenomena* 41

Caneva G., Gasperini R., Salvadori O., *Endolithic Colonization of Stone in Six Jewish Cemeteries in Urban Environment* 49

Dotter K. R., Smith B. J., McAlister J., Curran J., *Effects of Weathering Processes on Conservation Mortars and the Surrounding Stone Substrate* 57

Duffus P., Wangler T., Scherer G.W., *Swelling Damage Mechanism for Clay-Bearing Sandstones* 65

Duthie L., Hyslop E., Kennedy C., Phoenix V., Lee M. R., *Quantitative Assessment of Decay Mechanisms in Scottish Building Sandstones* 73

Espinosa Marzal R. M., Scherer G. W., *Study of the Pore Clogging Induced by Salt Crystallization in Indiana Limestone* 81

Fassina V., Gaudini G., Cavaletti R., *Condition Assessment of Marble Sculptures and Cleaning Procedures on Polychromed and Gilded Decorations of the Arca Scaligera of Cansignorio Della Scala in Verona* 89

Gaitán J.E., Sánchez R.V., Liñán C.R., de Hita P.R., <i>Evaluation of the Behaviour of Materials Used for the Restoration of the Town Hall of Seville</i>	97
Gomez-Heras M., Smith B.J., Viles H.A., <i>Laboratory Modelling of Gypsum Crust Growth on Limestone Related to Soot Pollution and Gaseous Sulphur: Implications of "Cleaner" Environments for Stone Decay</i>	105
Gralińska A., <i>Causes of Destructions of Nicolaus Copernicus Monument and Wielkopolska's Insurgents Monument Made of Artificial Stone. A Case Study</i> ...	113
Grossi C.M., Brimblecombe P., Menéndez B., Benavente D., Harris I., <i>Long Term Change in Salt Weathering of Stone Monuments in North-West France</i>	121
Gulotta D., Tedeschi C., Binda L., Toniolo L., <i>Durability of Porous Material to Salt Decay</i>	129
Hajpál M., <i>Heat Effect by Natural Stones Used by Historical Monuments</i>	137
Hamilton A., Hall Ch., <i>Crystallization of Sodium Sulfate Heptahydrate: Implications for Stone Decay</i>	145
Lazzarini L., Antonelli F., Cancelliere S., Conventi A., <i>The Deterioration of Euganean Trachyte in Venice</i>	153
Livingston R.A., <i>Mass Balance Study of Acid Rain Attack on the Statue of Phoenicia</i>	165
McCabe S., McKinley J. M., Smith B.J., <i>Simulating Initial Stages of Salt Accumulation and Organisation within Building Sandstones</i>	173
McKinley J.M., McCabe S., Smith B.J., <i>The Application of Geostatistical Analysis to the Prediction and Modelling of the Decay Dynamics of Masonry Materials</i>	181
Mitchell D.J., Searle D.E., <i>A Model Design to Evaluate Stone Deterioration in Polluted Urban Environments</i>	189
Nazel T., <i>Deterioration of Islamic Monuments in Cairo, Egypt – a Case Study on the Mausoleum of As-Saleh Nagm Ad-Din Ayyub</i>	199
Odgers D., Pinchin S., Martin B., Wood Ch., Curteis T., Doehne E., Chiari G., Teutonico J.M., Bourges A., <i>Investigations into Decay Mechanisms of Magnesian Limestone at Chapter House, Howden Minster</i>	211
Ortiz P., Guerrero M.A., Vázquez M.A., Ortiz R., Martin J.M., Peña M.C., <i>Accelerated Weathering Test as Environmental Behaviour Trials on Calcareous Stone</i>	223

Prokos P., Bala'awi F., <i>Salt Weathering in the Coastal Environment: a Thermodynamic Approach</i>	233
Rosato V.G., <i>Lichens on Religious Buildings in La Plata and Surrounding Area (Buenos Aires Province, Argentina)</i>	243
Saidov T., Pel L., <i>The formation of meta stable sodium sulfate heptahydrate during the drying as measured by NMR</i>	251
Shahidzadeh N., Rafai S., Bonn D., Wegdam G., <i>Salt Crystallization During Evaporation: Impact of Interfacial Properties</i>	257
Siedel H., v. Plehwe-Leisen E., Leisen H., <i>Salt Load and Deterioration of Sandstone at the Temple of Angkor Wat, Cambodia</i>	267
Smith B.J., Gomez-Heras M., Meneely J., McCabe S., Viles H.A., <i>High Resolution Monitoring of Surface Morphological Change of Building Limestones in Response to Simulated Salt Weathering</i>	275
Stefanidou M., Papayianni I., <i>The Porosity of Limestone and Its Behaviour to Salt Cycles</i>	283
Theoulakis P., Gerogiannis G., Stefanis N.A., Karatasios I., Zachos K., <i>Weathering Patterns on Excavated Marble Sculptures: Assessing the Values and Taking Conservation Decisions</i>	291
Török Á., Földes T., <i>Porous Limestone Decay: Detecting Changes by Using Computer Tomography</i>	299
Valentini F., Diamanti A., Bellezza S., Albertano P., Palleschi G., <i>Analytical Diagnosis of Stone Deterioration: a Comparison Between Different Substrata and Different Environments</i>	309
Van T., Al-Mukhtar M., <i>Durability Assessment of Tuffeau Limestone in Accelerated Weathering Tests</i>	317
Vázquez-Menéndez P., Esbert R.M., Alonso F.J., Ordaz J., <i>Evaluation of Damage Induced by Salt Crystalization in Granitic Building Stones</i>	325
Visser H., Gervais A., Lepper J., Stadlbauer E., Niemeyer R., Ehling A., Schubert J., Argow H., Pohlmann A., <i>Petrography, Composition and Characteristics of "Schilfsandstein" with Particular Reference to North West Germany and Weathering Behaviour in Historic Buildings</i>	333
Zurakowska M., Hughes J.J., Hyslop E., Kennedy C., Laing R., Young M.E., <i>Decay of Cleaned Sandstone Buildings in Scotland</i>	341

Theme 3 – Techniques and tools for conservation investigations

Bratasz Ł., Jakiela S., Lasyk Ł., Kozłowski R., <i>Direct Monitoring of Damage in Clay-Containing Sandstones by Acoustic Emission</i>	349
De Canio G., <i>Non-Invasive & No-Contact Seismic Early Warning Systems for Statues and Museal Objects</i>	357
Doehne E., Pinchin S., <i>Time-Lapse Macro-Imaging in the Field: Monitoring Rapid Flaking of Magnesian Limestone</i>	365
Emelyanov D.N., Volkova N.V., Kiselyova T.S., <i>Impregnation of Models of Stone Monuments with Solutions of Polybutyl Methacrylate in Mixture of Solvents</i>	373
Hauff G., Kozub P., D'ham G., <i>Which Cleaning Method is the Most Appropriate One? A Systematic Approach to the Assessment of Cleaning Test Panels</i>	381
Kamiński K., <i>Brick Walls Structural Moisture Content - a New Approach to Diagnostic Procedure</i>	389
Kapsalas P., Maravelaki-Kalaitzaki P., Zervakis M., Delegou E.T., Moropoulou A., <i>Towards Enriching the Estimation of Stone Degradation Through Computer Vision Analysis</i>	397
Kozub P., <i>To the Determination of the Young's Modulus from the Biaxial Flexural Strength</i>	407
Lawrence R.M.H., Walker P., <i>The Measurement of the Carbonation Profile in Lime Mortars Using a Drilling Resistance Measurement System</i>	415
Mecchi A.M., Poli T., Realini M., Sansonetti A., <i>A Proposal for a Common Approach in Choosing Tests for the Protocol Evaluation of Cleaning Methods</i>	425
Meinhardt-Degen J., Franzen C., Löther T., Weise S., <i>Application of Active Infrared Thermography for the Detection of Sub-Surface Defects in Historic Wall Paintings and the Assessment of Their Backfilling</i>	435
Myrin M., Malaga K., <i>Evaluation of Consolidation Treatment of Sandstone by Use of Ultrasound Pulse Velocity</i>	441
Pamplona M., Kocher M., Snethlage R., Aires-Barros L., <i>Drilling Resistance: State of the Art and Future Developments</i>	449
Pangallo D., Chovanová K., Šimonovičová A., De Leo F., Urzi C., <i>Assessment of the Biodeterioration Risk of the Ladislav Legend Fresco in Velka Lomnica (SK) Through Non-Invasive Methods</i>	457

Paradisi A., Pennati G., Carnelli D., Goidanich S., Toniolo L., <i>Mechanical Test for the Assessment of Plasters Consolidation Method</i>	465
Pintér F., Weber J., Bajnóczi B., <i>Visualisation of Solid Consolidants in Pore Space of Porous Limestone Using Microscopic Methods</i>	473
Pummer E., <i>Vacuum - Circulation – Process. Innovative Stone Conservation</i>	481
Rörig-Dalgaard I., Ottosen L.M., <i>Documentation of Electromigration Versus Electroosmosis in a Clay Brick under non Steady Laboratory Conditions</i>	489
Searle D.E., Mitchell D.J., <i>A Methodology for the Semi-Quantitative Analysis of Soiling Patterns on Building Façades in Bath, U.K. Using Digital Image Processing</i>	497
Seipt H., Simon S., Kozub P., <i>Ultrasonic Tomography: Correlation of Ultrasonic Velocity with Strength Parameters and Exemplary Application on Historical Stone Objects Using Virtual 3D – Models</i>	505
Skłodowski M., Snethlage R., Kocher M., <i>Micro Drill Cores - a New Tool for Testing Stones for Conservation Purposes</i>	513
Svahn Garreau H., Malaga K., <i>Tests of UPV and Karsten Pipes on Gotland Sandstone</i>	521
Tavukcuoglu A., Grinzato E., <i>Determination of Critical Moisture Content Level for Porous Materials by Quantitative IR Thermography</i>	529
Vergès-Belmin V., Rolland O., Leroux L., <i>Can We Be Confident in Colour Measurements Performed Outdoors?</i>	539
Weber J., Beseler S., <i>Marble Decay Under the Microscope: a Phenomenological Case Study on Sterzing Marble Sculptures from the Gardens of Schoenbrunn, Vienna</i>	547
Zammit G., De Leo F., Albertano P., Urzì C., <i>A Preliminary Study of Microbial Communities Colonizing Ochre-Decorated Chambers at the Hal Saftieni Hypogeum at Paola, Malta</i>	555

Theme 4 – Material structures, properties

Begonha A., Moutinho A., <i>Petrophysics of the Porto Granite Applied in the Santa Maria de Leça Church in Portugal</i>	563
Bourges A., Fehr K.T., Simon S., Snethlage R., <i>The Role of Pore Shapes in Elasticity Properties of Rocks</i>	573

Bourges A., Vergès-Belmin V., <i>A New Methodology to Determine Rheologic Behavior and Mechanical Properties of Desalination Poultrices</i>	581
Calcaterra D., Cappelletti P., Colella A., d'Albora M.P., Langella A., Morra V., de'Gennaro M., <i>Lava Stone in the Architecture of Campania Region</i>	589
Diekamp A., Konzett J., Wertl W., Tessadri R., Mirwald P.W., <i>Dolomitic Lime Mortar – a Commonly Used Building Material for Medieval Buildings in Western Austria and Northern Italy</i>	597
Doubravová K., Škrdlantová M., Kučerová L., <i>Mortars for Spongilite</i>	605
El-Gohary M., <i>Experimental Tests Used for Treatment of Red Weathering Crusts in Disintegrated Granite</i>	613
Galanos A., Doganis I., Maravelaki-Kalaitzaki P., Kallithrakas-Kontos N., <i>Hydraulic Mortars and Plasters at the Ancient Aqueduct of Naxos, Greece</i>	627
Hall Ch., Hoff W.D., Hamilton A., <i>Capillary Rise Dynamics in Masonry Structures: the Role of Water Flux in Long-Term Damage</i>	635
Hughes J.J., Nisbet S.M., <i>Petrographic Assessment of the Provenance of Historic Building Lime</i>	643
Hughes J.J., Tennent N.H., <i>The Petrography of the Giffnock Sandstone from the Interior of the Art Gallery and Museum, Kelvingrove, Glasgow</i>	651
Izaguirre A., Lanas J., Álvarez J.I., <i>A Research on Different Additives for Lime-Based Mortars to be Applied to Historical Monuments Restoration</i>	661
Karatasios I., Kilikoglou V., Theoulakis P., <i>Salt Resistance of Lime-Based Conservation Mortars Containing Barium Hydroxide</i>	669
Kracke T., Ruedrich J., Wedekind W., Mueller C., Siegesmund S., <i>Characteristics, Weathering Behaviour and the Effects of Consolidation Approaches on the Buntsandstein: a Case Study From the Bartholomew Cemetery in Goettingen</i>	677
Kramar S., Stopar D., Mirtič B., <i>Evaluation of Bioreceptivity of Some Slovenian Limestones</i>	685
Lindqvist J.E., Malaga K., Middendorf B., <i>Importance of Micro- and Macro-Porosity on Freeze-Thaw Behaviour of Natural Stones</i>	693
Obojes U., Mirwald P.W., Unterwurzacher M., Hofer R., <i>Study of the Petrographical and Petrophysical Properties of Spring Tufa and Hötting Breccia, Important Quaternary Building Stones of Historic Objects in Western Austria</i>	701

Papayianni I., Stefanidou M., Pachta V., <i>Design and Application of Artificial Stone Compatible to the Existing Old One in the Archaeological Site of Pella</i>	709
Pápay Z., Török Á., <i>Three Consolidants and Three Porous Limestones: Testing the Effectiveness of Consolidants on Hungarian Porous Limestones from Sósikút Quarry, in Terms of Physicomechanical Properties</i>	717
Pinińska J., <i>The Lublin Siliceous Carbonate Rocks. – a Medieval Building Material, its Geological Setting, Specific Properties and Deterioration Processes</i>	725
Poksińska M., <i>The Fresco Technique on Gypsum Substrate on Mediaeval Architectural Sculpture</i>	733
Procyk W., <i>Study of the Range and Effect of Post-Erosion Changes in Pore Spaces on the Improvement of Capillary Permeability in Royal Marbles</i>	739
Sansonetti A., Zerbi C.M., Biondelli D., <i>A Comparison of Gilding Techniques on Stuccoes Surfaces</i>	749
Siegesmund S., Ruedrich J., <i>Marble Bowing</i>	757
Spathis P., Charalambakis N., Christaras B., Kassoli-Fournaraki A., Papastergiadis E., <i>Building Materials, Deterioration Problems and Structural Conservation of Macedonian Tomb of Derveni Thessaloniki</i>	765
Válek J., Zeman A., <i>Properties of Historic Mortars in Relation to Technology of Their Production</i>	775
Author Index	xxv